

01 Engine oil level is too high, "Please reduce oil level" message in the instrument cluster

01 20 44 2054893/2 February 20, 2020. Supersedes Technical Service Bulletin Group 01 number 19-16 dated May 3, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, Q8	2019	All	3.0TFSI Turbo
A7, A8, S4, S5, S5 Cabriolet, S5 Sportback, and SQ5	2018 - 2019	All	3.0TFSI Turbo

Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised Technical Background (Added information)		
1	05/03/2019	Initial publication		

Customer states:

- "Please reduce Oil Level" message is shown in cluster or MMI.
- Engine Warmup Request message may also be present.

Technical Background

Fuel dilution in the engine oil due to multiple short trips in cold weather climate can occur, especially when the engine does not fully reach its operating temperature and fuel evaporation is not complete.

This condition can be mostly avoided by turning off start/stop until the engine is at operating condition.

Audi is currently investigating the conditions which lead to this issue. Please follow the steps outlined in this bulletin to correct the customer concern and provide Audi with valuable information to learn more about the issue.

Production Solution

Not applicable.



Service



Note:

For all warranty repairs, a completed Data Sheet must be uploaded for warranty claim payment. Failure to do so will result in non-payment of the claim. Before beginning, please print out the attached worksheet to record the following information.

1. Verify actual oil level using T40178 according to the Elsa Repair Manual. Record the measurement on the worksheet (see trackingsheet.pdf attachment).



Note:

If the oil level is not found to be above maximum, this bulletin does not apply. Do not continue to step 2.

- 2. Fill in the known information on the worksheet (Repair/In-Service date, mileage, customer driving profile, etc.) including the photograph for the actual warning shown in the vehicle (if still present).
- 3. Using ODIS, record the measured values (Figure 1). Save the log and upload to GFF Paperless.

Ölstandprüfung EA839 V6 3.0 TFSI

Name Gruppe		ifier	Kommentar Gruppe	
EnginOilTempe	1180	00151	Engine oil temperature	
EnginOilLevel	11BA	a description	Engine oil level	
EnginOilLevelActuaValue	58D1	100063	Engine_oil_level_actual_value	
EnginOilLevelTestProce1	1766	06569	Engine_oil_level_test_procedure_1	
EnginOilLevelTestProce1Quali		11302	Engine_oil_level_test_procedure_1_qualification	
EnginOilLevelTestProce2		10581	Engine_oil_level_test_procedure_2	
EnginOilLevelTestProce3		10582	Engine_oil_level_test_procedure_3	
EnginOilLevelTestProce3Quali	4F90	11303	Engine_oil_tevel_test_procedure_3_qualification	
OilLevelMeasuMaximValuePerce	4F80	11267	Oil_level_measurement_maximum_value_percent	
OilLevelMeasuMinimValuePerce	4F81	11268	Oil_level_measurement_minimum_value_percent	
EnginOilLevelHisto1	58D2	10064	Engine_oil_level_history_1	
EnginOilLevelHisto2	58D3	10065	Engine_oil_level_history_2	
EnginOilLevelHisto3	58D4	10066	Engine_oil_level_history_3	
EnginOilLevelHisto4	58D5	10067	Engine_oil_fevel_history_4	
EnginOilLevelHisto5	58D6	10068	Engine_oil_level_history_5	
EnginOilLevelHisto6	58D7	10069	Engine_oil_level_history_6	
EnginOilLevelHisto7	58D8	10070	Engine_oil_tevel_history_7	
EnginOilLevelHisto8	58D9	10071	Engine_oil_level_history_8	
EnginOilLevelHisto9	58DA	10072	Engine_oil_level_history_9	
EnginOilTempeMeasuValue	1632		Engine_oil_temperature_measured_value	
OilLevelAndOilTempeSensoSumpTem	1587	06570	Oil_level_and_oil_temperature_sensor_sump_temperature	
Anzahl automatische Starts				
Anzahl manueller Starts		2757	grün sind die Messwerte Bezeichnungen in ODIS unter Diag. Adr.	
0001				

Figure 1. Values to be uploaded to online GFF.

4. Perform an oil change on the vehicle according to ELSA Repair Manual



5. Upload the completed worksheet (including a picture of the warning) to Doc-IT. Please include the vehicle VIN in any filenames.

Warranty

Trair arrey			1			
Claim Type: • 110 up to 48 Months/50,000 Miles.						
	G10 for CPO Covered Vehicles – Verify Owner.					
	cal Service Bulletin	is				
Service Number:	1711					
Damage Code:	nage Code: 0010					
Labor Operations:	Record and upload tracking sheet information	1711 9999	80 TU			
	Perform oil change	1701 9999	30 TU			
Diagnostic Time:	GFF	No allowance	0 TU			
	Road test prior to service procedure	No allowance	0 TU			
	Road test after service procedure	0121 0004	10 TU			
Claim Comment:	ment: As per TSB #2054893/2					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
VAS 61XX	ODIS Service with VAS tester
T40178	Dipstick

Additional Information

All part and service references provided in this TSB (2054893) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.