

Condition

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
Atlas	2018 - 2019	3.6L (CDVC)	All	CA_JC000001	CA_KC999999	

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2058261/1	02/18/2020	01-20-01	Original publication.

One or more of the following fault codes may be stored in the Engine Control Module (ECM) Fault Memory:

Memory:	
DTC	Description
P0420	Catalyst System,Bank1 Efficiency Below Threshold
P0430	Catalyst System, Bank2 Efficiency Below Threshold
P0456	EVAP System Leak Detected (Very Small Leak)
P2096	Post Catalyst Fuel Trim System Too Lean Bank 1
P2097	Post Catalyst Fuel Trim System Too Rich Bank 1
P2098	Post Catalyst Fuel Trim System Too Lean Bank 2
P2099	Post Catalyst Fuel Trim System Too Rich Bank 2



Note:

DO NOT diagnose or replace components due to the above faults **before** performing the hardware replacement and update function as explained in this bulletin.

Technical Background

Catalytic converter hardware improved for long-term durability.

ECM software improved to reduce thermal stress on catalytic converter, prevent erroneous EVAP leak faults, and prevent erroneous fuel trim faults.

Page 1 of 8 plus attachment

	Technical Service Bulletin	Transaction No:	2058261/1
1	yst Replacement with Updated Programming DTCs	Release date:	2/18/2020
P0420, P0430, P	0456, P2096, P2097, P2098, or P2099		

Production Solution

Implemented improved catalyst and improved software at Start of Production (SOP) MY20.

Service



It is mandatory that both the catalytic converter replacement and the ECM software update are performed together!



Always refer to ETKA for the latest part number information.

Remove and replace the catalytic converter with part 3QF 254 500 MX, or part 3QF 253 059 PX, before proceeding to the ECM software update below. Refer to repair manual group 26 Exhaust System in Elsa.

Update-Programming Procedure:



Critical Warning: : The Midtronics battery charger must be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.



WARNING:

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Device Hardware & Windows® - VHW-20-02 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 6154 wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

Page 2 of 8 plus attachment

	Technical Service Bulletin	Transaction No:	2058261/1
	yst Replacement with Updated Programming DTCs	Release date:	2/18/2020
P0420, P0430, P	0456, P2096, P2097, P2098, or P2099		



To Update-Programming using Software Version Management (SVM), **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".


The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.



For MY18 Atlas vehicles: if the software update via SVM Unit Code is not successful, ensure that vehicle update 23X1 (if applicable to this VIN) has been successfully completed, before performing the Engine Control Module software update described in this technical bulletin.

• Update the Engine Control Module using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
			6024 6384			
		03H 906 026 E	6695	03H 906 026 E	9970	43E7
			7232			
			9930			
	3.6L	03H 906 026 F	6025	03H 906 026 F	9970	
MY18 Atlas	(CDVC)		6385			43E7
	(05 (0)		6696			1021
			9931			
			6026			
		03H 906 026 J	6389	03H 906 026 J	9970	43E7
		0011 300 020 0	6697	00/1 900 020 0		43L1
			9932			



		03H 906 026 R	6027 6416 6525 6692 9928	03H 906 026 R	9970	43E7
MY19 Atlas	3.6L (CDVC)	03H 906 026 S	6028 6417 6526 6693 9927	03H 906 026 S	9970	43E7
		03H 906 026 AA	6029 6418 6527 6694 9929	03H 906 026 AA	9970	43E7



The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.

	Technical Service Bulletin	Transaction No:	2058261/1
1	yst Replacement with Updated Programming DTCs	Release date:	2/18/2020
P0420, P0430, P	0456, P2096, P2097, P2098, or P2099		

Warranty



For Atlas models setting DTCs P0420 or P0430:

To determine if to and Procedures	•	covered under V	Varranty, always	refer to the Warra	anty Policies

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾							
Model(s)	Model(s) Year		Eng. Code(s)	Trans. Code(s)		Range om	VIN Range To
Atlas	2018	- 2019	3.6L (CDVC)	All	CA_JC000001 CA_KC99		CA_KC999999
	SAG						
Claim Type:		Use app	olicable Claim Ty	pe ¹⁾			
Service Num	nber:		Damage Code	нѕт			age Location nds on Service No.)
2673			0010	-	003		003
Parts Mai	nufacture	er	At	las	wwo ²⁾		
Labor Operation remove+reinstall		lytic conv	verter	26731990 = See Elsa for latest time units			
Labor Operation	າ³): Shiel	d remove	e+reinstall	26121990 = See Elsa for latest time units			
Labor Operation remove+reinstall			ld	24471990 = See Elsa for latest time units			
Labor Operation	1 3): Air h	ose remo	ove+reinstall	24381940 = See Elsa for latest time units			
Labor Operation	າ ³) : Batte	ery Charg	е	27068950 = See Elsa for the latest time units			
Labor Operation	າ ³⁾ : Upda	ate Progra	amming	See GFF Time expenditure			
Causal Part: Catalytic Converter			3QF 254 500 MX or 3QF 253 059 PX				
			Diagnos	tic Time ⁴⁾			
GFF Time exper	nditure		01500000 = 50 T	TU max		YES	
Road Test 01210004 = 10 T		·U		YI	ΞS		

Page 5 of 8 plus attachment

	Technical Service Bulletin	Transaction No:	2058261/1
	yst Replacement with Updated Programming DTCs	Release date:	2/18/2020
P0420, P0430, P	0456, P2096, P2097, P2098, or P2099		

Technical Diagnosis	01320000 = 00 TU max.	NO

Claim Comment: Input "As per Technical Bulletin 2058261" in comment section of Warranty Claim.

- 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.
- 2) Code per warranty vendor code policy.
- ³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.
- ⁴⁾ Documentation required per Warranty Policies and Procedures Manual.



Note:

For Atlas models setting DTCs P0456, P2096, P2097, P2098, or P2099:


To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Atlas	2018 - 2019	3.6L (CDVC)	All	CA_JC000001	CA_KC999999

SAGA Coding

Claim Type:	Use applicable Claim Type 1)				
Service Number:	Damage Code		HST		Damage Location (Depends on Service No.)
2470	2470 0039		-		-
Parts Manufacturer		At	las	WWO ²⁾	
Labor Operation 3): Catalytic converter remove+reinstall			26731990 = See Elsa for latest time units		
Labor Operation 3): Shiel	e+reinstall	26121990 = See Elsa for latest time units			
Labor Operation 3): Intake manifold remove+reinstall (upper part only)			24471990 = See Elsa for latest time units		
Labor Operation 3): Air hose remove+reinstall			24381940 = See Elsa for latest time units		
Labor Operation 3): Battery Charge			27068950 = See Elsa for the latest time units		

Page 6 of 8 plus attachment



Labor Operation 3): Update Progr	amming	See GFF Time expenditure		
Causal Part: Select Labor Operation	on	01500000		
Diagnostic Time ⁴⁾				
GFF Time expenditure	01500000 = 50 T	U max	YES	
Road Test	01210004 = 10 T	U	YES	
Technical Diagnosis	01320000 = 00 T	U max.	NO	

Claim Comment: Input "As per Technical Bulletin 2058261" in comment section of Warranty Claim.

Required Parts and Tools

Part No:	Part Description	Quantity	
3QF 254 500 MX	Catalytic Converter	1	
or			
3QF 253 059 PX			
N 102 861 08	Nut (at front of Catalyst)	6	
WHT 000 729 A	Bolt (for Heat Shield)	3	
3C0 253 115	Gasket (at front of Catalyst)	As needed (max 2)	
1K0 253 147 F	Retaining Ring (at rear of catalyst pipe)	As needed (max 1)	
03H 133 237 J	Large seal (for Intake Manifold)	As needed (max 2)	
03H 133 237 G	Small seal (for Intake Manifold)	As needed (max 4)	


Part numbers are accurate at time of publication. Always refer to ETKA for the latest part information.

¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.

⁴⁾ Documentation required per Warranty Policies and Procedures Manual.



Tool Description	Tool No:	
	GRX3000VAS	
Midtronics Battery Tester/Charger	or	
	MTRMSP0702 battery maintainer/charger	
	VAS 6150/X & VAS 6160/X and	
VAS Diagnostic Tool	ODIS Service with: current online updates	
Torque Wrench 1331 5-50Nm	VAG1331A or equivalent	
Elbow Assembly Tool	T10118	
Ratchet Insert Bit (to aid in engine oil dipstick removal)		
Ring Wrench 7-Piece Set	3337 or equivalent O2 socket	
Hot bolt paste	Refer to the Parts Catalog	

Tool numbers are accurate at time of publication. Always refer to ELSA for the latest tool information.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any convolkswagen vehicle to perform outside the normal parameters and specific Volkswagen Group of America / Volkswagen Group Canada.	•
voikswageri Group of America / voikswageri Group Canada.	
Date:	
Dealer Number:	
Vehicle Identification Number:	
Repair Order Number:	
	Dealer stamp
I, owner or driver of the above identified	Volkswagen, confirm:
Tuning" as described above (especially power increasing modificement on my vehicle.	cations) has NOT been
"Tuning" as described above has been performed on my vehicle and twere modified or installed:	the following components
TUNING was performed by (Please provide Company name and telephor to contact them):	ne number, if you wish us
I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions consequently VWGoA / VGC warranties.	
I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (delete any tuning program that was previously installed on the Control M vehicle.	estroy) and permanently
By signing below, I fully acknowledge and understand that the tuning propand VWGoA / VGC, will not be liable in any way for the loss of tuning date	•
Signature	of Customer