# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

MASTER WARNING LIGHT ON AND LACK OF POWER WITH DTC P2BF6:00

**Bulletin No.:** 01-004/20

Last Issued: 02/25/2020

#### APPLICABLE MODEL(S)/VINS

2019-2020 Mazda3 vehicles (Japan built) with VINS lower than JM1BP\*\*\*\*\*163205 (produced before Jan. 11, 2020)

2019-2020 Mazda3 vehicles (Mexico built) with VINS lower than 3MZBP\*\*\*\*\*131964 (produced before Jan. 11, 2020)

NOTE: Mexico spec. vehicles are not applicable as they are not equipped with Cylinder Deactivation.

## **DESCRIPTION**

Some customers may experience the master warning light turning on and a lack of power with DTC P2BF6:00 (Exhaust shutter valve position sensor circuit low input (1DC)) stored in memory. The PCM software has been modified to avoid the unnecessary warning light illumination and power restriction with no modification to the cylinder deactivation function.

Customers having this concern should have their vehicle repaired using the following repair procedure.

## REPAIR PROCEDURE

- 1. Verify customer concern.
- 2. Reprogram the PCM using the Mazda Diagnostic And Repair Software (MDARS). Refer to "MDARS ECU Reprogramming Procedure".

#### NOTE:

- If the current calibration file name in the ECU FILENAME screen is the same as shown in the Calibration Files Information or with a later suffix, reprogramming is not necessary.
- After reprogramming, pending DTC P2610:00 [PCM] will be stored without the Check Engine Light ON. Start the engine and clear the DTC.
- If DTC U2120:00 or/and U2500:82 are stored and i-ACTIVSENSE warning light (amber) turns on after the reprogramming, refer to SA-036/19.

Page 1 of 10

- 3. Clear the DTC, turn the ignition off, and get out of the vehicle.
- 4. Close and lock the door.
- 5. Wait for at least ten minutes.

6. Verify the repair by starting the engine and making sure that all warning lights are off. **NOTE:** If any DTC should remain after performing a DTC erase, diagnose the DTC according to the instructions on MGSS.


## **MDARS ECU Reprogramming Procedure**

**NOTE:** This procedure explains a generic reprogramming for all Electrical Control Units (ECU) such as PCM, BCM, ESU, etc. Be aware that some sentences and screen images below mention a certain control unit such as "PCM" or "BCM" as an example.

#### ATTENTION: READ ALL CAUTIONS AND NOTES BEFORE AND AFTER REPROGRAMMING!

#### **CAUTION:**

- A poor connection between the vehicle and M-MDS and/or low voltage may result in abnormal termination and/or data corruption. A low battery voltage may cause a reprogramming failure resulting in unexpected ECU replacement.
- Make sure that the following connections are firmly connected, then DO NOT touch the VCM and DLC cable to prevent noise and a poor connection.
  - Between the vehicle-side connector and the DLC cable
  - Between the PC-side connector and the USB port of the PC
- Connect an AC adaptor to the PC in order to minimize any voltage fluctuation during reprogramming. DO NOT use the vehicle battery as a power source for the PC.
- When reprogramming with MDARS, power consumption and voltage fluctuation are greater than with IDS. Connect the GR8 battery charger and use Manual Mode set to 14.5 volts and continuus charging to the vehicle to minimize any voltage fluctuation. DO NOT use any other charger.




Page **2** of **10** 

# BEFORE REPROGRAMMING NOTE:

- Turn off all electrical loads, especially the A/C blower, audio system, rear defogger and headlights.
- Perform a self-test and verify no DTCs are stored. If any DTCs are stored, repair the concern and delete the DTCs.
- Disconnect any aftermarket accessories (non-genuine Mazda accessories).
- Terminate all programs other than MDARS on the PC. Running other programs may interfere with the MDARS performance, resulting in the PC freezing or other problems.
- Perform reprogramming with a proper internet connection. When using a wireless network, make sure the connection is strong.
- Make sure to keep enough free space on the PC's hard disc. Insufficient free space (less than 1 GB) may result in the PC freezing during reprogramming.
- 1. Connect the M-MDS to the vehicle.
- 2. Launch the Mazda Diagnostic And Repair Software (MDARS).

Page 3 of 10

3. Turn the ignition on, then click "Start".



4. Select the "toolbox" tab.




### Page 4 of 10

#### 5. Select Work Support group.




6. Select "Software update", then click "Run".




### Page **5** of **10**

7. Select the ECU to be reprogrammed.



8. Confirm the current and new software versions, then click "Next". **NOTE:** When reprogramming the BCM, two softwares will be shown.




### Page 6 of 10


Bulletin No.: 01-004/20 Last Issued: 02/25/2020

9. Wait for the download, then click "Next".

NOTE: When reprogramming the BCM, downloading will occur twice.




10. Read the screen instructions, then click "Next".



### Page **7** of **10**


11. Follow the instructions on the screen, then click "Next".



12. Wait for the reprogramming to complete.

#### NOTE:


- The progress bar will stay at 90% for 30 seconds. This is not a failure.
- When reprogramming the BCM, this process will occur twice.




### Page 8 of 10

# AFTER REPROGRAMMING NOTE:

Select "Vehicle History" under "Collect Diagnostic Information", then click "Run".



Confirm the reprogramming on the screen and save the screen copy as a record.



### Page **9** of **10**

Bulletin No.: 01-004/20	Last Issued: 02/25/2020

# **CALIBRATION INFORMATION**

## Japan built

Trans- mission	Drive	File Name	PCM
M/T 2WD	PX58-188K2-K	Mitsubishi	
	2000	PX59-188K2-K	Denso
A/T		PX05-188K2-L	
		PX06-188K2-L	Denso
	// \ / I	PX07-188K2-N	
		PX08-188K2-N	Denso

#### **Mexico built**

A/T	/W/I)	PX13-188K2-F	Mitsubishi
		PX14-188K2-F	Denso
	ZL \/\/   )	PX15-188K2-F	Mitsubishi
		PX16-188K2-F	Denso

#### WARRANTY INFORMATION

#### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Fed. Emission Warranty.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	Α	
Symptom Code	6X	
Damage Code	9W	
Part Number Main Cause	5555-18-881	
Quantity	XXS1JXFX / 0.2 Hrs.	
Operation Number / Labor Hours:	XXS1JXFX / 0.2 Hrs.	

Page **10** of **10**