Advanced Technical Information

Bulletin #: 2003

Part ID: 2706

2

Y1A 12V Battery Creates a Warning and Gateway Fault Code P1B0200

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2020	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	February 3, 2020	Original document

Condition

The customer reports a warning in the instrument cluster associated with the 12 V Li-ion battery. The workshop confirms this warning along with fault code P1B0200 in the gateway. This fault is active and cannot be cleared in this condition.

In addition, this condition is sometimes accompanied by the 12 V system being dead and many associated faults and failures. At other times the vehicle 12 V system appears to function normally.

Technical Background

The 12 V Battery has failed and set a permanent fault in this condition. Since the battery cannot be recovered, it must be replaced.



Advanced Technical Information

Bulletin #: 2003

Part ID: 2706

2

Service Information

The current solution is to attempt to charge and recover the battery according to workshop manual procedures and attempt to clear the fault code (P1B0200). If this does not work, replace the 12 V battery. Take the same measures as usual to order this part (including submitting a parts support ticket where necessary).

If the vehicle's 12 V system is also depleted (that is, the battery state of charge is low and the vehicle behaves as a dead vehicle), please perform a quiescent current test and submit the results in PQIS. When more information becomes available, we will update this document.

Taycan Li-Ion 12 V Battery Hints

- When charging the 12 V Li-ion battery, continue to charge for at least 30 minutes.
- The battery control unit is integrated in the battery including a contactor relay which opens the electric circuit
 inside the battery in case of overcharge, deep discharge or overheating.

Warranty

Please be sure to fully document your findings in PQIS.

Use the following PQIS coding:

Cause location: 27060 Vehicle electrical system battery

Cause symptom: 6047 Diagnostic error

Search Items

P1B0200, LiFePO4, lightweight

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.