Advanced Technical Information

Bulletin #: 2004 Part ID: 2797

Y1A - Adjust Charger to 8A When Using 120V System

Vehicles Affected

| Ν | Nodels | Model Year | Model Type | VIN Range | Vehicle-Specific Equipment |
|---|--------|------------|------------|-----------|----------------------------|
| 1 | Taycan | 2020 | Y1A | N/A | N/A |

Revision History

| Revision | Release Date | Changes |
|----------|------------------|-------------------|
| 0 | February 7, 2020 | Original document |

Condition

The customer reports an inability to charge the Taycan using the provided charger with 120V. This information does not apply to Canada.

Technical Background

The Taycan will not charge with less than 800W of power. The provided charger has a default current setting of 6A. Using 120V, even in an ideal setting (with no losses), this would only provide 660W and the charger will not charge the vehicle.

The customer must adjust the current setting.

Service Information

To ensure constant charging, the customer must adjust the charger's allowed current to 8A. The following instruction set shows how to make this adjustment.

This information only applies to 120V power outlets. If the customer uses a 208/240V system, naturally, there is more power and this adjustment is not required.

Please reinforce to the customer Porsche's recommendation to charge with 208/240V charging when possible. 208/220V charging is much faster.



Advanced Technical Information

Bulletin #: 2004 Part ID: 2797 2

Taycan Customer Information

Your Taycan charger is capable of charging at 120V and 208/240V. For home charging, we highly recommend using the 208/240V cable whenever possible. Charging with 208/240V is much faster.

If you use 120V, you must adjust the charger's allowed current to 8A to ensure consistent charging. The following instruction set shows how to make this adjustment.



Figure A - Press the setting (gear) button.



Figure B - Press page down.



Figure C - Select "Adjust charging current".

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.



February 7, 2020 Page 2 of 2

Advanced Technical Information

Bulletin #: 2004 Part ID: 2797

2



Figure D - Adjust the current with the "+" button.



Figure E - The current should be set to 8A.

Search Items

charger, home charging, cable, cord, low power

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

