# HONDA

# Service Bulletin

20-013

# March 3, 2020

Version 1

# **RES Is Frozen with Cabin Watch Error Message**

# AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2018	Odyssey	EX-L with RES	ALL
2018	Odyssey	Touring, Elite	ALL
2019	Odyssey	EX-L with RES	5FNRL6HKB000001 thru 5FNRL6HKB021692
2019	Odyssey	Touring, Elite	5FNRL6HKB000001 thru 5FNRL6HKB021738

#### **SYMPTOM**

The RES screen will freeze or go blank while in use, and a **Camera System Problem. Image cannot be displayed** message appears on the Display Audio screen when using Cabin Watch (if equipped).

#### **POSSIBLE CAUSES**

The RES control unit may have a software or hardware issue.

#### **CORRECTIVE ACTION**

Check the RES control unit hardware and software versions. Based on your results, either replace the RES control unit or update its software.

## PARTS INFORMATION

Part Name	Part Number	Quantity
RES Control Unit (EX-L with RES)	39450-THR-A04	1
RES Control Unit (Touring and Elite)	39450-THR-A14	1

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

# **TOOL INFORMATION**

Tool Name	Tool Number
90 Degree FAKRA A Puller	07AAC-THRA100

# WARRANTY CLAIM INFORMATION

#### The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
0101M9	Check the RES control unit hardware version, and replace the RES control unit (EX-L).	0.6 hr	03214	03217	A20013A	39450-THR-A01
0101M9	Check the RES control unit hardware version, and replace the RES control unit (Touring and Elite).	0.6 hr	03214	03217	A20013B	39450-THR-A11
0105B2	Check the RES software version.	0.2 hr	03214	03217	A20013C	39450-THR-A11

Skill Level: Repair Technician

#### DIAGNOSIS

- 1. Enter the dealer diagnostics by pressing and holding the **HOME** icon, **Day/Night icon**, and the VOL/Power AUDIO knob, then select **Detailed Info**, **Unit Check**, **MOST Nodes**, and **RCU**.
- 2. Scroll down and check Hardware Version.
  - If you see A010 or A110, go to REPAIR PROCEDURE.
  - If you see A030 or A130, go to SOFTWARE INSPECTION/UPDATE PROCEDURE

RCU	RETURN
Connection diagnosis	OK
Secondary Part Name	2
Secondary Serial Number	2
Part Number	39450THR
Programming Date	08/01/2019
Hardware Version	(A030)
NetServices Version	
EHC Supplier	

#### SOFTWARE INSPECTION/UPDATE

- 1. Enter the dealer diagnostics by pressing and holding the **HOME** icon, **Day/Night** icon, the VOL/Power AUDIO knob, then select **Detailed Info**, **Unit Check**, **MOST Nodes**, and **RCU**.
- 2. Scroll up and check Software Version.

RCU	RETURN
Connection diagnosis	OK
Software Version	and the second
39452THR F0 39453THR A0	21 00
Company Name	Delphi
Part Name	Rear Control Box
Function Catalog Version	1.4
Serial number	162310965
Description	28549377

Is version 21 or higher displayed?

YES - The software is up to date. This bulletin does not apply. Continue with normal system troubleshooting.

**NO** - Update the software by way of **System Updates**. See 2018 or 2019 Front Control Box, Rear Entertainment System, and Navigation App.

## NOTE

If an Update Failed Code 57D message appears, check the internet connection and retry System Updates again.



#### **REPAIR PROCEDURE**

- 1. Disconnect the 12-volt battery.
- 2. Remove the glove box.
- 3. Remove the right side kick panel.
- 4. Remove the RES control unit.

# NOTE

Use the 90 Degree FAKRA A Puller (07AAC-THRA100) to remove the connectors from the RES control unit. See job aid *Using the MOST Connector Tools.* 



- 5. Remove the RES control unit bracket.
- 6. Install the RES control unit bracket to the new RES control unit.
- 7. Install the new RES control unit and bracket assembly.
- 8. Install the right side kick panel and the glove box. Then, reconnect the 12-volt battery.

END