

| | |
|----------------------------|-----------------------|
| REFERENCE: | Nova Bus Manuals |
| SECTION: | 16: Electrical System |
| RS N°: | MQR 7621-1881 |
| EFFECTIVE IN PROD.: | N/A |

APPLICATION DEADLINE: N/A

| | |
|-----------------------|---|
| SUBJECT: | Replacement of obsolete AIC3 module by AIC4 module at +RF2. |
| JUSTIFICATION: | Obsolete AIC3 module needs to be replaced by the newer AIC4 module. |

| LEVEL | DESCRIPTION | DIRECT CHARGES | | TIME |
|-------|-------------------------------------|----------------|----------|--------|
| | | LABOUR | MATERIAL | |
| 1 | Replace AIC3 module by AIC4 module. | Client | Client | 45 min |
| 2 | Install a USB adapter cable | Client | Client | 5 min |

| MATERIAL | | | | |
|-------------------------------------|----------|------|-----------------------|------------------|
| QTY | PART N° | REV. | DESCRIPTION | REPLACES PART N° |
| LEVEL 1 | | | | |
| 1 | N76971 | | Module AIC4 | – |
| 1 | 21816238 | | Display Adapter Cable | – |
| 5 | G5007996 | | Cable Tie Black 13.5" | – |
| | | | | – |
| LEVEL 2 (5 % of 79 vehicles) | | | | |
| 1 | 21875266 | | USB Adapter Cable | – |
| – | – | – | – | – |

To order, please contact Prevost Parts by phone at 1-800-771-6682, by fax at 1-888-668-2555 or by email at prevostparts.commandes@volvo.com. Specify document number, quantity of parts required and shipping address.

DISPOSAL OF PARTS

| | | | |
|---------------------------|------------------|-----------------|---|
| REMOVED PARTS ARE: | DISCARDED | RETAINED | * Dispose of the unused parts and the defective parts in accordance with local environmental standards in effect. |
| | X | – | |

REVISION HISTORY

| REV. | DATE | CHANGE DESCRIPTION | WRITTEN BY |
|------|----------|--------------------|------------|
| NR | 2020FE19 | Initial release | Nandan BS |

| CLIENT | ORDER | ROAD NUMBER | | VIN (2NVY/4RKY...) | | QTY |
|---|-------|-------------|------|--------------------|---------------|-----|
| | | FROM | TO | FROM | TO | |
| Central Oklahoma Transportation Authority | L619 | — | — | L82X7C3000367 | L82X7C3000367 | 1 |
| BC Transit - BCT - British Columbia | L604 | 9434 | 9434 | L82U5C3000597 | L82U5C3000597 | 1 |
| Minnesota Valley Transit Authority - MVTA | L706 | 4252 | 4258 | L82U4C4500127 | L82UXC4500133 | 7 |
| Ames Transportation Agency - Iowa | L707 | 660 | 661 | S92U5C4500159 | S92U1C4500160 | 2 |
| Austin - CMTA - Texas | L635 | 5001 | 5001 | S92U7C4500163 | S92U7C4500163 | 1 |
| BC Transit - BCT - British Columbia | L735 | 9435 | 9440 | L82U4C3000848 | L82U8C3000853 | 6 |
| BC Transit - BCT - British Columbia | L736 | 9441 | 9446 | L82U8D3000854 | L82U7D3000859 | 6 |
| Sudbury - Ontario | L740 | 831 | 833 | L82U1D3000887 | L82U5D3000889 | 3 |
| Austin - CMTA - Texas | L636 | 5002 | 5022 | S92U1D4500306 | S92U0D4500328 | 21 |
| University of Alabama - Alabama | L727 | 7026 | 7027 | L82U4D4500310 | L82U6D4500311 | 2 |
| LYNX - Florida | L725 | — | — | S92Y9D4500329 | S92Y5D4500330 | 2 |
| LYNX - Florida | L764 | — | — | S92Y7D4500331 | S92Y9D4500332 | 2 |
| Austin - CMTA - Texas | L704 | 5051 | 5068 | L82J7E4500471 | L82J2E4500488 | 18 |
| LYNX - Florida | L785 | — | — | S92L6E4500505 | S92L8E4500506 | 2 |
| University of Alabama - Alabama | L787 | 7028 | 7029 | L82J2E4500507 | L82J4E4500508 | 2 |
| MTD - Santa Barbara, California | L730 | — | — | S92J8E4500567 | S92J1E4500569 | 3 |

**WARNING**

FOLLOW YOUR INTERNAL SAFETY PROCEDURES.

PROCEDURE

- 1.1. Park the vehicle on an even surface with transmission in neutral (N).
- 1.2. Turn the ignition switch to OFF position and engage the parking brake.
- 1.3. Set the master control switch in the STOP position (see figure 1).




Figure 1 - Master Control Switch in STOP Position

- 1.4. Set the battery disconnect switch in the battery compartment to the OFF position (see figure 2).




Figure 2 - View of Battery Disconnect Switch

**CAUTION**

Before removing, dismantling or maintaining any electrical component the electrician should take the necessary precautions to avoid any risk of personal injury or damage to the equipment.

ACCESSING THE +RF2 PANEL

- 1.5. Unlock the driver's overhead panel door latches and lower the panel access door (see figure 3).



Figure 3 - Typical View of +RF2 Panel

REMOVING THE AIC3 MODULE

- 1.6. Locate the AIC3 module (see figure 4).
- 1.7. Disconnect the display connector and the green JAE type connectors.
- 1.8. Depending on the vehicle configuration, also disconnect the RJ-45 type connector and the Mitsumi USB type connector.
- 1.9. Remove and retain the four screws holding the AIC3 module to the +RF2 panel.
- 1.10. Remove the module from the panel.




Figure 4 - AIC3 Module Located on the Right Panel Section

INSTALLATION OF AIC4 MODULE

- 1.11. Using the previously retained screws, install the AIC4 module PN N76971 at the location where AIC3 was removed.
- 1.12. Reconnect the green connectors to the AIC4 module (reconnect the RJ-45 connector if present).
- 1.13. Connect the display adapter cable PN 21816238 between the AIC4 module VGA connection and the display cable previously disconnected (see figure 5 & 6).




Figure 5 - Display Adapter Cable



Figure 6 - Rear View of AIC4 Module



NOTE

If a Mitsumi (USB) connector type has been disconnected from AIC3 module then continue with Level 2 procedure using USB adapter cable PN 21875266.

PROGRAMMING THE AIC4 MODULE

- 1.14. Program the AIC system using the program and revision shown in the table entitled "AIC programs List" or the one recommended by your customer support manager. See Section 16: Advanced Information Centre from your maintenance manual for the programming procedure under the heading "Reprogramming".

AIC program List

| CLIENT | ORDER | ROAD NUMBER | | VIN (2NVY/4RKY...) | | QTY | PROGRAMS |
|---|-------|-------------|------|--------------------|---------------|-----|----------------|
| | | FROM | TO | FROM | TO | | |
| Central Oklahoma Transportation Authority | L619 | — | — | L82X7C3000367 | L82X7C3000367 | 1 | AIC4FW_USA_S_I |
| BC Transit - BCT - British Columbia | L604 | 9434 | 9434 | L82U5C3000597 | L82U5C3000597 | 1 | AIC4FW_BCT_S_I |
| Minnesota Valley Transit Authority - MVTA | L706 | 4252 | 4258 | L82U4C4500127 | L82UXC4500133 | 7 | AIC4FW_USA_S_I |
| Ames Transportation Agency - Iowa | L707 | 660 | 661 | S92U5C4500159 | S92U1C4500160 | 2 | AIC4FW_USA_S_I |
| Austin - CMTA - Texas | L635 | 5001 | 5001 | S92U7C4500163 | S92U7C4500163 | 1 | AIC4FW_AUS_S_I |
| BC Transit - BCT - British Columbia | L735 | 9435 | 9440 | L82U4C3000848 | L82U8C3000853 | 6 | AIC4FW_BCT_S_I |
| BC Transit - BCT - British Columbia | L736 | 9441 | 9446 | L82U8D3000854 | L82U7D3000859 | 6 | AIC4FW_BCT_S_I |
| Sudbury - Ontario | L740 | 831 | 833 | L82U1D3000887 | L82U5D3000889 | 3 | AIC4FW_SUD_D_I |
| Austin - CMTA - Texas | L636 | 5002 | 5022 | S92U1D4500306 | S92U0D4500328 | 21 | AIC4FW_AUS_S_I |
| University of Alabama - Alabama | L727 | 7026 | 7027 | L82U4D4500310 | L82U6D4500311 | 2 | AIC4FW_ALA_S_I |
| LYNX - Florida | L725 | — | — | S92Y9D4500329 | S92Y5D4500330 | 2 | AIC4FW_USA_S_I |
| LYNX - Florida | L764 | — | — | S92Y7D4500331 | S92Y9D4500332 | 2 | AIC4FW_USA_S_I |
| Austin - CMTA - Texas | L704 | 5051 | 5068 | L82J7E4500471 | L82J2E4500488 | 18 | AIC4FW_AUS_S_I |
| LYNX - Florida | L785 | — | — | S92L6E4500505 | S92L8E4500506 | 2 | AIC4FW_USA_S_I |
| University of Alabama - Alabama | L787 | 7028 | 7029 | L82J2E4500507 | L82J4E4500508 | 2 | AIC4FW_ALA_S_I |
| MTD - Santa Barbara, California | L730 | — | — | S92J8E4500567 | S92J1E4500569 | 3 | AIC4FW_USA_S_I |



NOTE

* Please contact your customer support manager to get the program or an up-to-date revision of it.

- 1.15. Using cable ties PN G5007996, secure the display adapter cable and make sure there is no interference and rubbing when closing the panel.

CLOSING THE +RF0 PANEL

- 1.16. Raise the panel door.
- 1.17. Lock the overhead panel door latches.
- 1.18. Place the master control switch in ON position.
- 1.19. Set the battery disconnect switch in the battery compartment to the ON position.
- 1.20. The vehicle may be returned to service. ❖

LEVEL 2**NOTE**

This level is applicable if a USB cable with a Mitsumi type connector must be connected to the new AIC4 module.

- 2.1. Connect the USB adapter cable PN 21875266 between the AIC4 module USB connection and the Mitsumi type connector previously removed (see figure 6 & 7).




Figure 7 - USB Adapter Cable

- 2.2. Go to " PROGRAMMING THE AIC4 MODULE" Section.