



SIB 51 05 20 FUEL FILLER DOOR STICKING

2020-02-10

MODEL

E-Series	Model Description
G06	X6 Sports Activity Coupe
G07	X7 Sports Activity Vehicle

SITUATION

The fuel filler door may be sticking, requiring multiple attempts to open.

CAUSE

The fuel filler door material can swell in wet conditions, causing the filler door to stick.

CORRECTION

Modify the fuel filler door.

PROCEDURE



1. Remove the fuel tank filler flap following repair instructions **REP 41 63 000** "Removing and installing the fuel filler flap".

Inspect the white label on the hinge arm (circled).

For G07: Are the last 2 digits less than 10?

Yes: Continue to step 2

No: This bulletin does not apply

For G06: Are the last 2 digits less than 09?

Yes: Continue to step 2

No: This bulletin does not apply



2. This is the area which will be modified (circled). **Do not modify the lower tab, only the upper.**

3. Remove 0.7 mm from the upper tab



(arrow) using a file. A feeler gauge can be used (shown lying flat along top edge) to assist with measuring.



4. Close the filler flap and measure the distance between the upper tab and the filler door assembly. The gap must be at least 0.1 mm.



5. Open the filler door to measure the slotted opening of the filler flap as shown to the left.

6. Enlarge the slotted opening by 1 mm by filing away the edge (arrows).

Note: File only the outer edges of the slotted opening, do not file the center section.



7. Apply a 5 mm section of butyl inside each locking tab of the filler door, in the area shown to the left.



8. The photo to the left shows correct installation of butyl.

9. Reassemble the vehicle.

PARTS INFORMATION

Part Number	Description	Quantity
83 22 2 159 535	Butyl cord (D=4 mm, L=10 m)	Sublet as needed
Or		
81 22 0 441 263	Butyl cord (D=1.5 mm, L=10 m, W=15 mm)	Sublet as needed
Or		
83 19 0 153 321	Butyl cord (D=1.5 mm, L=10 m, W=20 mm)	Sublet as needed

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	5117023400	Stop pad including ejector for fuel filler flap sluggish
Labor Operation	Description	Labor Allowance
41 63 000	Removing and installing the fuel filler flap (Main work)	Refer to AIR

Or:		
41 63 500	Removing and installing the fuel filler flap (Plus work)	Refer to AIR
And:		
51 00 001	Work time to modify the fuel filler door	3 FRU

If you are using a Main labor code for another repair, use the Plus code labor operation 41 63 500 instead of 41 63 000.

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 51 00 001 is not considered a Main labor operation. Also, since the work time FRU allowance to be claimed is specified, a separate punch time is not required. However; it still requires an explanation on the repair order and in the claim comments section.

And, as needed:

Sublet – Bulk Materials (RO and Claim Comments Required)

Sublet Code 4	See the sublet reimbursement calculations below	Reimbursement for the repair-related bulk materials (Do not use the BMW part numbers for claim submission)
----------------------	---	--

Sublet reimbursement calculation for claiming the applicable repair-related bulk materials (BMW part numbers) is at the dealer net price amount for the quantities used plus your center's handling.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section.