



# Technical Service Bulletin

**01 MIL on, DTC P008700, P21F500, P21F400, P218700, P21F800, and/or P217700 stored in the ECM**

01 20 47 2051014/2 March 11, 2020. Supersedes Technical Service Bulletin Group 01 number 18-63 dated April 16, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS3 and TTRS	2017 - 2018	All	2.5 TFSI

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Updated Note) Revised <i>Warranty</i> (Added Claim Type and updated Labor Operation)
1	04/16/2018	Initial publication

### Customer statement:

- MIL on with poor performance.

### Workshop findings:

One or more of the following DTCs is stored in the engine control module (ECM), J623 (address word 0001) about the fuel measuring system:

- **DTC P008700** (fuel rail/system pressure too low).
- **DTC P21F500** (fuel measuring system 2, bank 1 system too rich from idle speed).
- **DTC P21F400** (fuel measuring system 2, bank 1 system too lean from idle speed).
- **DTC P218700** (bank 1, fuel measuring system too lean at idle speed).
- **DTC P21F800** (fuel measuring system 2, bank 1 system too lean at idle speed).
- **DTC P217700** (bank 1, fuel measuring system too lean from idle speed).

## Technical Background

Issue is currently under investigation.



# Technical Service Bulletin

---

## Production Solution

Not applicable.

## Service

Erase the DTC and release the vehicle back to the customer.



### Note:

Parts replacement does not resolve this issue. Claims for replaced parts will be subject to review.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• 1E1 up to 8 Years/80,000 Miles (Service Number 2470 Only).</li><li>• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	2470		
<b>Damage Code:</b>	0039		
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on the diagnostic protocol (Max 20 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB #2051014/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions*.



# Technical Service Bulletin

---

All part and service references provided in this TSB (2051014) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

**©2020 Audi of America, Inc.** All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.