


Service Bulletin


TECHNICAL

Subject: Ticking, Rattle and/or Buzzing Noise Heard from inside Passenger Compartment, Possible Fuel Leak

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	-				L86	
	Escalade ESV					L86	
Chevrolet	Suburban					L83	
	Tahoe	2015	2020			L83	
GMC	Yukon Models					L83, L86	
	Yukon XL Models					L83, L86	

Involved Region or Country	North America, Middle East, Europe, Russia, Chile, Columbia, Ecuador and Peru.		
	Some customers may comment on the following condition:		
	A rattling and/or ticking noise that may be louder inside the vehicle than outside.		
	⇒ The noise may be picked up at the back of the left valve cover, and/or underneath the vehicle near middle of the driver's door.		
Condition 1	⇒ This noise will be noticeable at idle, most noticeable in the 700-900 RPM range.		
	\Rightarrow The noise may also sound like a lifter tick.		
	\Rightarrow This may also be called a fuel line buzz or ringing noise.		
	• While the rattle is occurring, the S-shape portion of the fuel feed line, right in front of the tank, will be vibrating / rattling.		
	Some customers may comment on a fuel leak.		
Condition 2	Diagnosis that the fuel leak is originating from the fuel feed line at the molded-in clip on top of tank.		
	The rattling, ticking noise may be caused by the check valve in the low pressure fuel feed jumper line at the engine not fully seating, allowing pressure pulses from the high pressure side back into the low pressure side of the fuel system.		
Cause	These pressure pulses could cause the S-shaped portion of the fuel feed line, in front of the tank, to vibrate and/or rattle		
	If the S-shaped portion of the fuel line rattles over a period of time, the fore-aft motion in the line could result in wear. This wear could result in a fuel leak where the line is secured into the molded-in clip on the tank.		





Service Procedure

Install a new low pressure fuel feed jumper line at the engine, and replace the original design fuel feed line at the tank with the appropriate updated design PN listed in the Parts table, following the procedure below.



Low pressure fuel feed jumper pipe at engine



4870639




4863828



4863840

Updated design fuel feed line at tank

Note: Summarized below are key notes for both the low pressure fuel feed jumper pipe at the engine and the low pressure chassis fuel feed pipe at the tank. Refer to Fuel Feed Pipe Replacement (At Engine) and Fuel Feed Pipe Replacement (At Tank) for complete procedures.



- 1. Replace the low pressure fuel feed jumper pipe (1) at the engine.
- 2. Lower the fuel tank assembly and remove from the vehicle.
- 3. Remove the low pressure chassis fuel feed pipe from the fuel tank.

Note: Provide protection for the fuel feed port on the fuel pump module.



4. Using shop air, clean the fuel feed pipe run channel on the tank to remove dirt and debris.



4863840

5. Position the updated design fuel feed pipe to the fuel tank and make connection to the fuel pump module.

4863833



4864117

- 6. Install the fuel line into the tank molded-in clip and ensure the line is fully seated.
- 7. Install the fuel tank to the vehicle.
- 8. Validate the vibration / rattle in the fuel line has been eliminated.

Parts Information

Causal Part	Description	Part Number	Qty
х	Pipe Asm-Fuel Feed (Jumper at Engine)	12618338	1
х	Hose Asm-Fuel Feed (at Tank) (Updated Design, SWB)	84200271	1
Х	Hose Asm-Fuel Feed (at Tank) (Updated Design, LWB)	84200274	1

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4081878*	Fuel Feed Pipe Replacement at Engine and Tank	2.7 hrs
*This is a unique Labor Operation for Bulletin use only.		

Version	3
Modified	Released September 22, 2017 Revised August 08, 2018 - Added 2018 and 2019 Model Year and removed cutoff dates. Revised February 03, 2020 - Added 2020 to Model Year.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION