

Technical Information

150/19_{ENU} 9110

Service

9

Symptom in Vehicle Interior - Air Bubbles in Laminate of Front Display and Control Unit (PCM display): Subsequent Work on Dashboard (SY 150/19)

Model line:	Cayenne (9YA)
Model Year:	2019
Subject:	Front display and control unit (PCM display)
Symptom:	Air bubbles occur in laminate of front display and control unit (PCM display):



Air bubbles in the PCM display (example)

- Cause: Due to insufficient gap dimensions, the dashboard can press sideways onto the front display and control unit (PCM display).
- RemedialIn the event of a customer complaint, the top corners of the dashboard must be reworked. The front
display and control unit (PCM display) must be replaced.

Required spare parts

Spare Parts:	Part No.	Designation	Qty.
	9Y0919597G OV3	\Rightarrow Display	1 ea.

Preparatory work

Work Procedure: 1 Remove front display and control unit; see \Rightarrow Workshop Manual '911019 Removing and installing display + control unit'.

Rework switch panel



Information

When working on the dashboard, make sure not to damage the surface in any of the visible areas.

Work Procedure: 1 Shave a millimetre off the top left corner of the dashboard \Rightarrow Reworking the top left corner of the dashboard -1- using a suitable tool (e.g. a round file).



Reworking the top left corner of the dashboard

2 Shave a millimetre off the top right corner of the dashboard \Rightarrow *Reworking the top right corner of the dashboard*-1-using a suitable tool (e.g. a round file).

AfterSales

Technical Information



Reworking the top right corner of the dashboard

3 Remove any dust produced using a microfibre cloth.

Concluding work

- Work Procedure: 1 Install front display and control unit; see \Rightarrow Workshop Manual '911019 Removing and installing display + control unit'.
 - 2 Code front display and control unit; see ⇒ Workshop Manual '911055 Replacing front display and control unit'.

Invoicing

Invoicing: For documentation and warranty invoicing, enter the labor operations, PQIS coding and part numbers specified below in the warranty claim:

APOS	Labor operation	l No.
70184100	Repairing the dashboard	

PQIS coding:

Location (FES5)	91103	PCM display
Damage type (SA4)	3045	swollen

9 911	Service 10 ENU 150/19		Technical Information
Parts Info:	Part No. 9Y0919597G OV3	Designation ⇒ Display	Qty. 1 ea.
References:	\Rightarrow Workshop Manual	911019 Removing and installi	ng front display and operator control unit'

 \Rightarrow Workshop Manual '911055 Replacing front display and operator control unit'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

 $\ensuremath{\textcircled{}^{\odot}}$ 2020 Porsche Cars North America, Inc.

Mar 13, 2020 Page 4 of 4

AfterSales