

Technical Information

144/19_{ENU} 9215

Service

Complaint - Windshield Wiper Touching A-Pillar: Adjusting Wiper Angle (144/19)

Model line:	Cayenne (9YA)
Model Year:	As of 2018
Subject:	Windshield wiper motor
Information:	The windshield wiper on the driver's side is touching the A-pillar at the top turning point.
Remedial Action:	Adjust wiper angle using the PIWIS Tester.

Required tools

Tools:

• 9900 - PIWIS Tester 3 with installed PIWIS Tester software version 38.900.000 (or higher)

Battery charger with a current rating of at least 90 A, e.g. V A S 5 9 0 8 / battery charger 90 A.

NOTICE

Fault entry in the fault memory and/or control unit coding aborted due to low voltage.

- Increased current draw during diagnosis or control unit coding can cause a drop in voltage, which can result in one or more fault entries and the abnormal termination of the coding process.
- ⇒ Before getting started, connect a suitable battery charger with a current rating of at least 90 A to the jump-start terminals.

NOTICE

Control unit coding will be aborted if the WiFi connection is unstable.

- An unstable WiFi connection can interrupt communication between the PIWIS Tester and the vehicle communication module (VCI). As a result, coding may be aborted.
- ⇒ During control unit coding, always connect the PIWIS Tester to the vehicle communication module (VCI) via the USB cable.

NOTICE

Control unit coding will be aborted if the driver's key is not recognized

- If the driver's key is not recognized in the vehicle, coding cannot be started or will be interrupted.
- ⇒ Place the driver's key with the back facing down into the front left storage compartment in the centre console to guarantee a continuous radio link between the vehicle and the driver's key.

Technical Information

Work Procedure:



Information

The procedure described here is based on the PIWIS Tester 3 software version **38.900.000**.

The PIWIS Tester instructions take precedence and in the event of a discrepancy, these are the instructions that must be followed. Deviations may occur with later software versions, for example.

- 1 Connect a battery charger with a current rating of **at least 90 A**, e.g. **Battery Charger, 90 A**, to the jump-start terminals in the engine compartment and switch it on, see ⇒ *Workshop Manual* '270689 Charging vehicle electrical system battery'.
- 2 Position the driver's key in the rear area of the left cupholder in the centre console between the holding struts (emergency start tray) in order to guarantee a permanent radio link between the vehicle and driver's key ⇒ *Emergency start tray*.
- 3 Adjust wiper angle.
 - 3.1 Connect the **PIWIS Tester** to the vehicle and switch it on.
 - 3.2 Switch on the ignition.
 - 3.3 Start diagnostics.
 - 3.4 Select "Front-end electronics (BCM1)" control unit.
 - 3.5 Select the "Maintenance/repairs" tab.
 - 3.6 Select the menu item **"Windshield wiper motor, reduce wiper angle"** and press F12" to continue.
 - 3.7 Follow the instructions on the Tester.
- 4 Switch off the ignition.
- 5 Disconnect the PIWIS Tester from the vehicle.
- 6 Switch off and disconnect the battery charger.

Invoicing

Invoicing: For documentation and warranty invoicing, enter the labor operation and PQIS coding specified below in the warranty claim:

APOS	Labor operation	I No.
92152500	Programming wiper motor	



Emergency start tray

AfterSales

Technical Information

9

PQIS coding:

Location (FES5)	92150	Wiper motor
Damage type (SA4)	1100	Incorrect adjustment

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.

AfterSales

Mar 20, 2020 Page 3 of 3