

Technical Information

16/20 ENU WLB1

Service

9

WLB1 - Removing Adapter Cable in Left Fuse Box (Workshop Campaign)

Vehicle type:	Taycan (Y1A)			
Model Year:	2020			
Subject:	Left fuse box			
Information:	To prevent the 12-volt vehicle electrical system battery from being discharged by the instrument cluster in transport mode, an adapter cable for terminal control of the instrument cluster was installed in the left fuse box on the affected vehicles.			
	Due to the modified terminal control, the instrument cluster is only switched on and off via the ignition in transport mode.			
	Information This remedial action must always be carried out during the sales check.			
Remedial Action:	Remove the adapter cable from the left fuse box.			
Affected Vehicles:	Only vehicles assigned to the campaign (see also PCSS Vehicle Information).			
Remove adapter cable in left fuse box				

- Work Procedure: 1 End operational readiness manually. Press and hold the start/stop button for 3 seconds until the instrument cluster switches off for this purpose.
 - 2 Unclip the cover on the fuse box in the left footwell \Rightarrow Unclipping the cover from the footwell fuse box-1-.



Unclipping the cover from the footwell fuse box

AfterSales

3 Disconnect the adapter cable \Rightarrow Disconnecting the adapter cable -1 - at the bottom row in the fuse box \Rightarrow Disconnecting the adapter cable -2-.





Disconnecting the adapter cable

- 4 Remove the security cover → *Fitting the security cover*-1- from the glove compartment and fit it to the bottom row in the fuse box → *Fitting the security cover*-arrow-.
- 5 Clip in the fuse box cover in the left footwell.



Fitting the security cover

AfterSales

Technical Information

6 Unclip the side cover for the fuse box in the dashboard \Rightarrow Unclipping the fuse box cover in the dashboard -1-.

7



Unclipping the fuse box cover in the dashboard

Disconnecting the adapter cable

8 Remove the fuse (yellow, 20 A) from the glove compartment and insert it **in slot 8** of the fuse box ⇒ *Insert the fuse* **-1**-.

Disconnect the other end of the adapter cable \Rightarrow Disconnecting the adapter cable -1- \Rightarrow Disconnecting the adapter cable -2- from the fuse box and remove it between the A-pillar trim panel and dashboard.



Insert the fuse

- 9 Remove the security cover ⇒ Clipping in the security cover -1-from the glove compartment and fit it onto the fuse box ⇒ Clipping in the security cover -arrow-.
- 10 Clip in the side cover for the fuse box in the dashboard.
- 11 Check that the instrument cluster is working correctly. Manually stop and restore operational readiness for this purpose.



Clipping in the security cover

Result of check	Action required	
Instrument cluster remains switched on (OK)	Continue with Concluding work.	
Instrument cluster switched off (NOK)	Check that the fuse (yellow, 20 A) is inserted correctly in slot 8 of the side fuse box in the dashboard.	
	If it is inserted correctly and the instrument cluster remains switched off, remove the fuse (yellow, 20 A) and use a suitable tester to measure the resistance.	



Information

Please note that transport mode must be deactivated immediately after carrying out the remedial action in order to prevent the 12-volt vehicle electrical system battery from becoming discharged.

12 Deactivate transport mode during the sales check. For instructions, see \Rightarrow Workshop Manual '010100 Sales check.'

Warranty processing

Scope:

Working time:

Remove adapter cable in left fuse box Includes: Connecting and disconnecting battery charger

Labor time: 10 TU

AfterSales

Technical Information	Service	
	16/20 enu WLB ²	9

Check instrument cluster operation

 \Rightarrow Damage Code WLB1 66 000 1

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

 $\ensuremath{^{\odot}}$ 2020 Porsche Cars North America, Inc.

AfterSales