SERVICE BULLET

COPYRIGHT@ NISSAN NORTH AMERICA, INC.

Reference: EL19-059a ITB19-042a April 27, 2020

INFINITI: AV CONTROL UNIT REPLACEMENT PROCESS

This bulletin has been amended. See AMENDMENT HISTORY on the last page. Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2020 Q50 (V37)

> 2020 Q60 (V37) 2020 QX50 (J55) 2020 QX80 (Z62)

IF YOU CONFIRM

The AV control unit needs to be replaced on an APPLIED VEHICLE.

ACTION

Classification:

IMPORTANT: The AV control unit for the Applied Vehicles is new, different from the previous model year, and requires a new procedure when replacing. If the following steps are not followed completely, all features will not work as intended.

- Read and save the VIN
- 2. Read and save the configuration
- 3. Replace the AV control unit
- 4. Reprogram the AV control unit
- 5. Configure the AV control unit
- 6. Write the VIN to the AV control unit

IMPORTANT: Procedures 4-6 above **must** be performed in the order shown below.

ORDER OF COMPLETION

REPROGRAM AV control unit



CONFIGURE



WRITE VIN to AV control unit

IMPORTANT: The purpose of ACTION (above) is to give you a guick idea of the work you will be performing. You MUST closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

SERVICE PROCEDURE

NOTICE

Perform the following before starting the reprogramming procedure to prevent damage to the control unit:

- Connect the AC Adapter to the CONSULT PC.
- Connect the CONSULT PC to the internet (Wi-Fi or cable).
- Ensure ASIST on the CONSULT PC has been synchronized (updated) to the current date and all C-III plus software updates (if any) have been installed.
- Turn OFF all external Bluetooth® devices (e.g., cell phones, printers, etc.) within range of the CONSULT PC and the VI. If Bluetooth® signal waves are within range of the CONSULT PC during reprogramming, the reprogramming may be interrupted.
- Turn OFF all vehicle electrical loads.
- Connect a battery maintainer or smart charger, set to reflash mode or a similar setting, to ensure the battery voltage stays between 12.0 V and 15.5 V.

READ AND SAVE THE VIN

NOTE: If the VIN data cannot be saved, proceed to step 19 on page 9. You will be instructed to manually enter the VIN later in the procedure.

1. Select **Diagnosis** (One System).




Figure 1

2. Select **MULTI AV**.




Figure 2

- 3. Select Work support.
- 4. Select **SAVE VIN DATA**.
- 5. Select **Start**.




Figure 3

6. Select **Start**.




Figure 4

7. Wait for the Current status to show Completed, and then select **End**.




Figure 5

8. Select Home.

READ AND SAVE THE CONFIGURATION

9. Select **Re/programming**, **Configuration**.




Figure 6

NOTE: C-III plus screens for steps 10-13 are not shown.

- 10. Read the on-screen Precaution and select **Confirmed Instructions** at the bottom of the screen.
- 11. Select **Next**.
- 12. Confirm the vehicle details are correct for the vehicle you are working on, and then select **Confirm**.

5/30

13. Confirm the correct VIN, and then select **Confirm**.

ITB19-042a

14. Select **MULTI AV**.




Figure 7

15. Select **Before ECU Replacement**.




Figure 8

16. Write down all Setting Values.

HINT: Use arrows to view all Setting Value screens.




Figure 9

17. Select Save.




Figure 10

18. Select **End**.




Figure 11

REPLACE THE AV CONTROL UNIT

- 19. Replace the AV control unit.
 - Refer to the ESM, section DRIVER INFORMATION & MULTIMEDIA > AUDIO, VISUAL & NAVIGATION SYSTEM > INFINITI INTOUCH > REMOVAL AND INSTALLATION > AV CONTROL UNIT.

REPROGRAM THE AV CONTROL UNIT

20. Select Re/Programming, Configuration.




Figure 12

NOTE: C-III plus screens for steps 21-25 are not shown.

- 21. Select Confirmed instructions.
- 22. Select Next.
- 23. Select Confirm.
- 24. Confirm the correct VIN is populated.
- 25. Select Confirm.

26. Select Other Operation.

NOTE: If the VIN could not be read/saved, proceed to step 27.




Figure 13

27. Select MULTI AV.




Figure 14

28. Select After ECU Replacement from the Programming (Blank ECU) menu.




Figure 15

29. Select Next.




Figure 16

30. Select Manual selection.




Figure 17

31. Use the arrows to scroll to the next page, and then select **Next**.




Figure 18

32. Review Table A, below, and find the applicable ROM Data ID for the vehicle you are working on.

Table A

Model	System	ROM Data ID		
2020 OE0	BOSE	283C2 6HL5C		
2020 Q50	NON-BOSE	283C2 6HL5D		
2020 Q60	BOSE	283C2 5CR0B		
	NON-BOSE	283C2 5CR0A		
2020 QX50	BOSE	283C2 5NY1A		
	NON-BOSE	283C2 5NY0A		
2020 QX80	BOSE	283C2 6JF0B		
	NON-BOSE	283C2 6JF0A		

- 33. Use the arrows to scroll to locate and select the applicable **ROM Data ID**.
- 34. Select Next.




Figure 19

35. Confirm the information matches the vehicle you are working on, and then select **Next**.




Figure 20

36. Follow the on-screen instructions, and then select **Next**.




Figure 21

37. Confirm the battery voltage is within acceptable limits, and then select **Start**.




Figure 22

- 38. Select your user group from the drop down menu.
- 39. Select **OK**.




Figure 23

40. Enter your username and password, and then select **Submit**.




Figure 24

41. Wait for the data transfer to complete (Figure 26) and then select **Next**.




Figure 25 Figure 26

42. Follow the on-screen instructions, and then select **Next**.




Figure 27

- 43. Erase all DTCs.
 - Follow the on-screen instructions to erase the DTCs by turning the ignition OFF and then ON, and then wait for the erase to complete.
- 44. Confirm the before and after part numbers are different, and then select **Next**.




Figure 28

WRITE THE CONFIGURATION FROM SAVED DATA (From Read/Save)

45. Select **Re/programming**, **Configuration**.




Figure 29

- 46. Read the on-screen **Precaution** and select Confirmed instruction on the lower left side of the screen.
- 47. Select Next.




Figure 30

48. Confirm the correct vehicle information is populated, and then select **Confirm**.




Figure 31

49. Confirm the correct Saved Data Detail, and then select **Confirm**.




Figure 32

50. Use the arrows to confirm all Setting Values, and then select **OK**.




Figure 33

51. Wait for the data transfer to complete, and then select **End**.




Figure 34

WRITE CONFIGURATION MANUALLY (Manual Selection)

52. Select Re/programming, Configuration.




Figure 35

NOTE: C-III plus screens for steps 53-55 are not shown.

- 53. Confirm the on-screen instructions, and then select **Next**.
- 54. Confirm the vehicle details, and then select **Confirm**.
- 55. Confirm the correct VIN is populated, and then select **Confirm**.

56. Select **MULTI AV**.




Figure 36

57. Select **After ECU Replacement** under the <u>VEHICLE CONFIGURATION</u> section.




Figure 37

58. Select Manual selection.




Figure 38

59. Use the drop down menu to select the values that were written down in step 16 on page 7.

HINT:

- Use the arrows to scroll to any additional pages.
- The selections shown may not reflect the features of your vehicle.

60. Select Next.




Figure 39 Figure 40

61. Confirm the correct setting values, and then select **OK**.

HINT: Use the arrows to scroll to any additional pages.




Figure 41 Figure 42

62. Select **End** after the configuration has been successfully written.




Figure 43

WRITE THE VIN FROM SAVED DATA (From Read/Save)

HINT:

- If the VIN data was saved using steps 1 7, continue to step 63.
- If the VIN data was **NOT** saved using steps 1 7, skip to step 69 on page 27.

63. Select Diagnosis (One System).




Figure 44

64. Select MULTI AV.




Figure 45

- 65. Select the Work support tab.
- 66. Select WRITE VIN (SAVED DATA).
- 67. Select Start.




Figure 46

68. Confirm the correct VIN is displayed, and then select **Start**.




Figure 47

WRITE THE VIN MANUALLY (Manual Input)

69. Select Diagnosis (One System).




Figure 48

70. Select **MULTI AV**.




Figure 49

- 71. Select the **Work support** tab.
- 72. Select WRITE VIN (MANUAL INPUT).
- 73. Select **Start**.




Figure 50

74. Manually type the VIN into the fields shown below.

HINT: The VIN must be entered two times.

75. Select **Start**.




Figure 51

- 76. Follow the on-screen instructions to verify the VIN was written successfully.
 - The VIN should now populate in the field shown below.




Figure 52

77. Select **End**.




Figure 53

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace AV Control Unit – Q50 Auto	(1)	RX8SAA RX8TAA	ZE	32	1.9
Replace AV Control Unit – Q60 Auto					1.9
Replace AV Control Unit – QX50 Auto					1.5
Replace AV Control Unit – QX80 Auto					1.7
Replace AV Control Unit – Q50 Manual	(1)				1.9
Replace AV Control Unit – Q60 Manual					1.9
Replace AV Control Unit – QX50 Manual					1.6
Replace AV Control Unit – QX80 Manual					1.7

⁽¹⁾ Reference the electronic parts catalog and use the Navigation Control Assembly (25915-*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 26, 2019	ITB19-042	Original bulletin published
April 27, 2020	ITB19-042a	Information on page 1 updated.