

01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430

Release date: 4/21/2020

Condition**Applicable Vehicles**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2018	3.6L (CDVC)	All	CA_JC000001	CA_JC999999

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2058261/4	4/21/20	01-20-01	Meta data correction
2058261/3	4/20/20	01-20-01	MY19 removed due to campaign action.
2058261/2	03/16/2020	01-20-01	Moving DTC codes P0456, P2096, P2097, P2098, P2099 to Technical Bulletin 2058272.
2058261/1	02/18/2020	01-20-01	Original publication.

**Tip:**

This software update also includes modifications for: DTCs P0456, P2096, P2097, P2098, and P2099.

One or more of the following fault codes may be stored in the Engine Control Module (ECM) Fault Memory:

DTC	Description
P0420	Catalyst System,Bank1 Efficiency Below Threshold
P0430	Catalyst System, Bank2 Efficiency Below Threshold

**Note:**

DO NOT diagnose or replace components due to the above faults **before** performing the hardware replacement and update function as explained in this bulletin.



01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430

Release date: 4/21/2020

Technical Background

Improved catalytic converter hardware for long-term durability.

Improved ECM software to reduce thermal stress on catalytic converter.

Production Solution

Improved catalytic converter and improved software implemented at Start of Production (SOP) MY20.

Service



Note:

It is mandatory that both the catalytic converter replacement and the ECM software update are performed together!



Tip:

Always refer to ETKA for the latest part number information.

- Remove and replace the catalytic converter with part 3QF254500MX, or part 3QF253059PX, before proceeding to the ECM software update below. Refer to repair manual group 26 Exhaust System in Elsa.

Update-Programming Procedure:



Note:

Critical Warning: : The Midtronics battery charger must be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.



WARNING:

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!

**01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430**

Release date: 4/21/2020

**Note:**

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Device Hardware & Windows® - VHW-20-02 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 6154 wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

**Tip:**

To Update-Programming using Software Version Management (SVM), **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

**Note:**

For MY18 Atlas vehicles: if the software update via SVM Unit Code is not successful, ensure that vehicle update 23X1 (if applicable to this VIN) has been successfully completed, before performing the Engine Control Module software update described in this technical bulletin.

- Update the Engine Control Module using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
MY18 Atlas	3.6L (CDVC)	03H 906 026 E	6024	03H 906 026 E	9970	43E7
			6384			
			6695			
			7232			
			9930			
		03H 906 026 F	6025	03H 906 026 F	9970	43E7
			6385			
			6696			

**01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430**

Release date: 4/21/2020

			9931			
		03H 906 026 J	6026 6389 6697 9932	03H 906 026 J	9970	43E7
		03H 906 026 AA	6029 6418 6527 6694 9929	03H 906 026 AA	9970	43E7

**Tip:**

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.

01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430

Release date: 4/21/2020

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Atlas	2018	3.6L (CDVC)	All	CA_JC000001	CA_JC999999
SAGA Coding					
Claim Type:		Use applicable Claim Type ¹⁾			
Service Number:	Damage Code	HST		Damage Location (Depends on Service No.)	
2673	0010	-		003	
Parts Manufacturer		Atlas		WVO ²⁾	
Labor Operation ³⁾ : Catalytic converter remove+reinstall			26731990 = See Elsa for latest time units		
Labor Operation ³⁾ : Shield remove+reinstall			26121990 = See Elsa for latest time units		
Labor Operation ³⁾ : Intake manifold remove+reinstall (upper part only)			24471990 = See Elsa for latest time units		
Labor Operation ³⁾ : Air hose remove+reinstall			24381940 = See Elsa for latest time units		
Labor Operation ³⁾ : Battery Charge			27068950 = See Elsa for the latest time units		
Labor Operation ³⁾ : Update Programming			See GFF Time expenditure		
Causal Part: Catalytic Converter			3QF 254 500 MX or 3QF 253 059 PX		
Diagnostic Time ⁴⁾					
GFF Time expenditure		01500000 = 50 TU max		YES	
Road Test		01210004 = 10 TU		YES	

01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430

Release date: 4/21/2020

Technical Diagnosis	01320000 = 00 TU max.	NO
Claim Comment: Input "As per Technical Bulletin 2058261" in comment section of Warranty Claim.		
1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only. 2) Code per warranty vendor code policy. 3) Labor Time Units (TUs) are subject to change with ELSA updates. 4) Documentation required per Warranty Policies and Procedures Manual.		

Required Parts and Tools

Part No:	Part Description	Quantity
3QF 254 500 MX or 3QF 253 059 PX	Catalytic Converter	1
N 102 861 08	Nut (at front of Catalyst)	6
WHT 000 729 A	Bolt (for Heat Shield)	3
3C0 253 115	Gasket (at front of Catalyst)	As needed (max 2)
1K0 253 147 F	Retaining Ring (at rear of catalyst pipe)	As needed (max 1)
03H 133 237 J	Large seal (for Intake Manifold)	As needed (max 2)
03H 133 237 G	Small seal (for Intake Manifold)	As needed (max 4)
Part numbers are accurate at time of publication. Always refer to ETKA for the latest part information.		

Tool Description	Tool No:
Midtronics Battery Tester/Charger	GRX3000VAS or MTRMSP0702 battery maintainer/charger

**01-20-01 - Catalyst Replacement with Updated Programming DTCs
P0420 or P0430**

Release date: 4/21/2020

VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X and ODIS Service with: current online updates
Torque Wrench 1331 5-50Nm	VAG1331A or equivalent
Elbow Assembly Tool	T10118
Ratchet Insert Bit (to aid in engine oil dipstick removal)	
Ring Wrench 7-Piece Set	3337 or equivalent O2 socket
Hot bolt paste	Refer to the Parts Catalog
Tool numbers are accurate at time of publication. Always refer to ELSA for the latest tool information.	

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal.
Always check with your Parts Dept. and Repair Manuals for the latest information.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)


*) "TUNING" is described as the addition of or modification of any component which causes a Volkswagen vehicle to perform outside the normal parameters and specifications approved by Volkswagen Group of America / Volkswagen Group Canada.

Date: _____

Dealer Number: _____

Vehicle Identification Number: _____

Repair Order Number: _____



Dealer stamp

I _____, owner or driver of the above identified Volkswagen, confirm:

☐ "Tuning" as described above (especially power increasing modifications) has NOT been performed on my vehicle.

☐ "Tuning" as described above has been performed on my vehicle and the following components were modified or installed:

TUNING was performed by (Please provide Company name and telephone number, if you wish us to contact them):

I understand that if my Control Module is determined to have been tuned, any damage caused by the tuning of the Control Module (including adverse emissions consequences) will not be covered by VWGoA / VGC warranties.

I am permitting an authorized Volkswagen Dealer to reflash (update) my Control Module, and by doing so, I understand that this process will automatically overwrite (destroy) and permanently delete any tuning program that was previously installed on the Control Module of my Volkswagen vehicle.

By signing below, I fully acknowledge and understand that the tuning program will not be restored and VWGoA / VGC, will not be liable in any way for the loss of tuning data.

Signature of Customer