04/28/2020

### **Technical Service Bulletin**

### **72K4 UPDATE**

# **Checking Outer Backrest Frame – (NVLW)**



Applicable Vehicles				
Model(s) Year		VIN Range	Vehicle-Specific Equipment	
Q7	27 2019 See Campaign/Action screen in Elsa		See Campaign/Action screen in Elsa	

Revision History			
Revision	Date	Purpose	
1	April 28, 2020	Original publication	

# **Technical Background**

This Update has been proactively released to prevent the following condition(s) from occurring in the vehicle:			
Criteria	riteria Technical Background		
4M	Cracks may, in isolated cases, occur in the cross member of the front seat backrests. This may result in the wiring harness becoming damaged on the sharp edge of the crack on the left seat. Diagnosis would detect the damaged wiring harness. A crack in the cross member for the front seat backrests does not constitute a structural problem.		

# Remedy

Criteria	Remedy
4M	Inspect the left front seat backrest frame and replace if necessary.

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the **72K4** code in the Elsa Campaign/Action Information screen on the day of repair.
- Vehicle must be within the New Vehicle Limited Warranty.
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

April 2020 72K4 Page 1 of 7

04/28/2020

#### **Technical Service Bulletin**

#### **72K4 UPDATE**


### **Checking Outer Backrest Frame – (NVLW)**




### **Service**

#### **NOTE:**

- Elsa is the only valid inquiry/verification source. Check Elsa on the day this vehicle UPDATE will be performed to verify vehicle eligibility for the UPDATE. Status must show "open". Attach an Elsa printout showing the "open" status to the repair order.
- If this UPDATE appears to have already been performed but the code still shows open in Elsa, contact Warranty before proceeding further. Another dealer may have recently performed this UPDATE but not yet entered a claim for it in the system.
- Elsa may also show additional open action(s); if so, inform your customer this work can be done while the vehicle is in for this UPDATE.
- Contact the Warranty Helpline (U.S.) or the Warranty Campaign Specialist (Canada) if you have any questions.





• Enter the VIN in Elsa and proceed to the "Campaign/Action" screen.

### i TIP

On the date of repair, print this screen and keep a copy with the repair order.

- Confirm the Campaign/Action is open <arrow 1>. If the status is closed, no further work is required.
- Note the Applicable Criteria ID <arrow 2> for use in determining the correct work to be done and corresponding parts associated.



 All Safety Recalls must be completed prior to completing this campaign.

first.

April 2020 72K4 Page 2 of 7

**Release Date** 


04/28/2020

### **Technical Service Bulletin**

### **72K4 UPDATE**

# **Checking Outer Backrest Frame – (NVLW)**





- Remove the backrest cover panel on the left front seat:
  - See ELSA Repair Manual: Repair manual > Body Interior > 72 Seat Frames > Front Seats > Backrest Cover, Removing and Installing

April 2020 72K4 Page 3 of 7


04/28/2020

### **Technical Service Bulletin**

### **72K4 UPDATE**

# **Checking Outer Backrest Frame – (NVLW)**





- Disengage left coupling hook <arrow 1> on side of outer backrest frame.
- Disengage piping <arrow 2> on outer backrest frame.



 Inspect the backrest frame in the area shown <arrow>.

### • NOTE

Backrest frame shown completely removed for clarity. The frame does not need to be completely removed.

### **Technical Service Bulletin**

### **72K4 UPDATE**

### **Checking Outer Backrest Frame – (NVLW)**





Check outer backrest frame with an inspection mirror.

### **A** CAUTION

Avoid checking the component by feel with your hand, as there may be sharp edges in the area of the crack. These edges may constitute an injury risk.



- If there are no cracks present:
  - Outer backrest frame does not require replacement.
  - Reassemble vehicle in the reverse order of disassembly.
  - Work is complete.
- If cracks are present:
  - Outer backrest frame must be replaced.

April 2020 72K4 Page 5 of 7

**Release Date** 

04/28/2020

#### **Technical Service Bulletin**

### **72K4 UPDATE**

### **Checking Outer Backrest Frame – (NVLW)**



# Warranty

#### **Claim Entry Instructions**

After Update has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the Elsa screen print showing action open on the day of repair to the repair order.

If customer refused campaign work or vehicle is out of the specified warranty parameter for this Update:

- ✓ <u>U.S. dealers:</u> Submit the request through Audi Warranty Online under the <u>Campaigns/Update</u> option.
- ✓ Canada dealers: Upload the repair order to Audi WIN/Operations/Campaign Closure.

Service Number	72K4			
Damage Code	0099			
Parts Vendor Code	002			
Claim Type	Sold vehicle: 7 10 Unsold vehicle: 7 90			
Causal Indicator	Mark labor as causal part			
Vehicle Wash/Loaner	Do not claim wash/loaner under this action			
Criteria I.D.	4M			
	Check left front outer backrest frame, no cracks present, no further work required			
	LABOR			
	Labor Op	Time Units	Description	
	0183 00 99	20	Inspect outer backrest frame, no further work required	
-OR-	Check left front outer backrest frame, cracks present, replace outer backrest frame			
		LABC	PR	
	Labor Op	Time Units	Description	
	7219 55 99	230	Replace outer backrest frame	
	PARTS			
	Quantity	Part Number	Description	
	1.00 See ETKA Front seat backrest frame			

April 2020 72K4 Page 6 of 7

Release Date

04/28/2020

#### **Technical Service Bulletin**

### **72K4 UPDATE**

# **Checking Outer Backrest Frame – (NVLW)**



Additional Actions Some of the affected vehicles may be involved in additional Actions. Please check your

Elsa Campaign/Action Information screen so that any additional required work can be

done simultaneously.

Verifying Vehicle Eligibility To verify vehicle eligibility for this Update, *always* check the Elsa Campaign/Action Information screen. The Elsa system is the *only* binding inquiry and verification system;

other systems are not valid and may result in non-payment of a claim.

Help for Claim Entry For questions regarding claim entry, contact Audi Warranty.

Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

Required Customer Notification

# **Required Parts (if necessary)**

Criteria	Quantity	Part Number	Part Description	Ordering Method
4M	1	SEE ETKA	Left front seat outer backrest frame	P.O.C.

 Properly store (retain), destroy or dispose of removed parts in accordance with all state/province and local requirements, unless otherwise indicated and/or requested through the Warranty Parts Portal (WPP) for U.S. and the Part Destruction and Core Disposition Report for Canada.

### **Additional Information**

All parts and service references provided in this Update are subject to change and/or removal. Always check Elsa for the most current version of this document.

April 2020 72K4 Page 7 of 7