

# **Preliminary Information**

# PIP5691A 1.3L (RPO L3T) Engine Exchange Program-Gasoline

#### Models

Brand:	Model:	Model Years:	VIN:		Engino	Transmissions
Dianu.			from	to	Engine:	Transmissions:
Buick	Encore GX	2020	All	All	1.3L (L3T)	All
Chevrolet	Trailblazer	2021	All	All	1.3L (L3T)	All

Involved Region or Country	North America
Condition	Engine Exchange
Cause	New Product Monitoring

This PI will cover the engine exchange program only for the 2020-2021 model listed above.

Additional PIs will be published for each engineer component as they are introduced.

During the launch of the 2020-2021 model yearthe following engine will be under an exchange program:

#### 1.3L Engine Assembly (RPO L3T)

Product teams continually seek valuable information for engineering improvements.

To assist in this effort, an engine exchange program will be used for the listed engine and vehicles

The 2020 model year engine exchange program will be administered by the GM Product Quality Center (PQC).

Dealerships are required to call the PQC, not GM &chnical Assistance (TAC), to request an exchange.

Please contact the Product Quality Center (PQC) by opening a new case via Dealer Case Management (DCM) From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.

Then in Global Connect click on the Support/Chat tab, TAC-PQC Tab, PQC -Parts Restrictions Templates to Download the PQC PIP5692 2020 Buick Encore GX or 2021 Chevrolet Traiblazer 1.2L (LIH) Engine Exchange Template and save a copy to your computer, You can attach a copy of the template to your PQC Case.

Guidelines for honoringexchange requests under this program are being strictly enforced.

The PQC may refer the dealer technician to TAC if additional diagnosis is required.

TAC will be available for product inquiries that do not require assembly replacement.

Division	PQC Telephone Number	
US Cars and Trucks	1-866-654-7654	
Canada English and French		

Components that may be removed and serviced without exchange are identified by an "X" in the appropriate column of the table below

Any repairs involving engine components not identified in the table belowengine noise concerns, oil consumption, or relatedsymptoms may require an engine exchange.

Important: Engine block and internal components along with any component in which a cylinder head has to be removed to perform the repair will require an engine exchange.

Please note that this list is subject to change as the program progresses.

You will be notified by the PQC consultant if additional items are considered serviceable on a particular engine.

Serviceable Components	1.3L (L3T)
Accessory Drive	x
A/C Compressor	x
All Engine Sensors	X
All Cooling System Hoses	X
Brackets	X
Camshaft Cover	X
Camshaft Cover Heat Shield	X
Camshaft Position Actuator Solenoid Vilve	x
Catalytic Converter	x
Coolant Control Valve / Gaskets	x
Coolant Pump Electric	x
Coolant System Pipes	x
Cooling System RadiatorInlet/Outlet Pipes	x
Crankcase Pressure Sensor	x
Crankshaft Dampner	X
Crankshaft PositionSensor	X
Crankshaft Position Sensor Ring	X
Engine Control Module(ECM)	x
Engine Cover / BeautyCover	x
Engine Oil Cooler and Pipes	x
Engine Wiring Harness	X
	X

Flywheel / Flexplate	
Fuel Injector Wiring Harness	X
Fuel Injectors	X
Fuel Pipes & HP Fuel Pump Assembly	X
Fuel Rail	x
Generator	X
Heater Outlet /Inlet Fittings	X
Hi / Lo Pressure Fuel Lines	х
Ignition System(Coil, Spark Plugs)	X
Intake Air Ducts & Related Components	X
Intake Air Temperature Sensor	X
Intake Manifold / Gasket	X
Knock Sensors	X
Map or Baro Sensor	X
Mass Air Flow Sensor	X
Oil Cooler / Pipes	X
Oil Fill Cap	X
Oil Filter	X
Oil Level Indicator(Dipstick)	X
Oil Pressure ControlSolenoid Valve	X
Oil Pressure Switch	X
Oxygen Sensors	X
Purge Pump , Lines and Solenoid	X
Starter Motor Assembly	X
Throttle Body / Adapter / Gaslet	X
Turbocharger Wastegate Control Sdenoid	X
Turbocharger Wastegate Tubes and Hoses	X
Turbo Assembly / POA parts / Brackets / Gaskets	X
Vacuum Pump Assembly	X


Important: Engine repairs or failures that arecaused by components external to the engine do NOT fall under the exchange program. For example, if an engine failure is caused by incorrectly installed engine coolant lines, the engine assembly (or parts required to complete a repair) must be obtained from General Motors Customer Care and Aftersales (GMCC&A) through the normal parts ordering process. The exchange program is created as a way to correct internal concerns and to take what is learned and find a way to eliminate these concerns. External components causing a failure do not provide any useful information in improving an engine. The engine received from GMCC&through the normal parts ordering process will be a new service engine.

### **Engine Broadcast Code Location**


#### 1.3L Engine Assembly(RPO L3T)

### **General Location:**





# **Specific Location:**





As shown in the abovephotos, the engine broadcast code can be found on the engine front cover just above the harmonic balancer

#### **Procedures:**

A thorough diagnosis must be performed on the condition in order to prevent unnecessary component replacements.

Contact the Product Quality Center (PQC) to verify the proper diagnosis has been performed.

Upon review of the diagnosis, the PQC will establish a case reference number and mæk arrangements for shipping an exchangeunit to your dealership.

The replaced engine must be returned to the Warranty Parts Center (WPC).

DO NOT SHIP AN ENGINE TO THE (WPC) WITHOUT AN OFFICIAL WPC REQUEST

Important: Failure to return the replaced engine by the due date will result in the dealershipeing debited the entire warranty claim (parts and labor).

The removed unit must be returned complete in the original exchange shipping container

For effective engineering analysis, please do not remove any components.

Dress items on the removed unit must remain the same as the replacement engine (e.g., exhaust manifolds, throttle body etc.). Dealerships returning engines/components that have been even partially disassembled will be judged as violating this procedurend, as such, will be billed for all materials furnished.

Notice: The exchange unit will be shipped with a quantity of oil; check oil level before starting engine.

### **WPC Request:**

The Warranty Parts Center (WPC) will fax a Special Art Request to your dealership requesting the return of the removed engine.

DO NOT wait for the warranty claim to be paid before returning the removed engine.

The Special Part Request will provide a request number

This request number must be written on the outside of the return container using a permanent marker.

Failure to write the request number on the return container may delay the processing of your return.

If you do not receive the WPC Special **B**rt Request, contact Julie Cumo at 248-371-9939 (for **F**ench call PQC 1-866-654-7654)to obtain the proper paperwork in order to return the removed engine. Failure to return the engine may result in a debit.

### **Shipping Preparation:**

- 1. Remove the engine assembly/component as outlined in the applicable Service Manual.
- 2. Drain all fluids from the removed engine.
- 3. Retorque any fasteners that were loosened or removed to the original torque specification.
- 4. Remove any plastic shipping plugs and covers from the exchange unit and install them on the removed unit.
- 5. If the concerned engine leaks, mark the area directly on the engine with a permanent mack
- 6. Write the PQC case reference number on the repair order form.
- 7. Write the PQC case reference number directly on the component in a visible location.
- 8. Insert a copy of the WPC Special **A**rt Request, repair order with technician comments, and the completed OEM EngineExchange Worksheet (template in this bulletin) into a plastic bag and securely fastento the engine.
- 9. Place the removed engine into the original shipping container

### **Shipping Instructions:**

- 1. Write the WPC request number and the PQC case reference number on the outside of the container with a permanent marker.
- 2. U.S. Dealers Please go to wwwgmwpc.com, click on the UPS emblem, enter your BAC and select "dealer inquires." Select "available forms" located on the left side of the screen in blue, the select "Central Transport BOL." A partially complete BOL will appearPlease print this Central Transport BOL and fill out "from" section with your dealer information and complete the description fields.

Canadian Dealers - Refer to the latest version of Corporate Bulletin Number 99-00-89-019 for detailed shipping information.

- 3. Contact the specified carrier to arrange for pick-up of the removed engine. If lift gate service is necessary, please request it at the time of arranging pick-up service.
- 4. Have the driver sign the bill of lading. Retain a copy of the signed bill of lading. Attach your cop to the original repair order. This will be your proof of returning the removed engine.
- 5. Ship all return exchanges/components Third Brty Freight Collect with appropriate paperwork to

GM Warranty Parts Center 45 Northpointe Drive Orion, MI 48359

# **OEM Engine Exchange Template**

•	Caller's Name/Position:
•	Parts Manager name:
•	Technician Direct Phone:
•	Dealership's Fax Number:
•	Parts Dept fax number:
•	Customer Concern:
•	Have you completed the "OEM Engine Exchange template in bulletin and reviewed Serviceable Components?
•	(If no, you MUST complete Bulletin and calback)
•	Has the vehicle been modified with non-productionaccessories?
•	What type of service is the vehicle being usedn (police, taxi, towing, personal, etc.)?
•	Describe the failure of the engine:
•	Broadcast Code:
•	Engine Serial Number:
•	Replacement Cost = \$
•	Requested Labor Time:
•	Are there any leaks (Y/N)
•	If no, continue to next question
•	If yes,
•	What type of leak?
•	Location of the leak?

• Are there any Noises (Y/N)
If no, continue to next question
• If yes, complete the following
What kind of noise?
• Location and frequency of the noise?
When does is occur?
How long does it last?
Any Lubrication Concerns (Y/N)
If no, continue to next question
If yes, complete the following
Oil pressure readings:
Results of oil consumption test:
Was the oil contaminated?
• If yes, what type of contamination?
<ul> <li>Any Performance Concerns (Y/N)</li> <li>If no, continue to next question</li> </ul>
• If yes, List
• Low power?
Misfire?
• Detonation?

Blue smoke?
White smoke?
Will engine crank?
Vibration?
Did the engine show evidence of the following
Overheating? (Y/N)
Coolant consumption? (Y/N)
Coolant contamination? (Y/N)
Low compression? (Y/N)

## Warranty Information

If yes, List Compression test readings:

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor TimeParts Allowance
4067490	Engine	Use Published Labor Operation
4067490	Replacement	Time
For engine exchange only: a \$400.00 misc. net allowance for the engine can be claimed in the warranty		
transaction		

Important: Applicable miscellaneous items such as engine oil and coolant should be added to the part allowance amount and claimed in the Parts Cost column and not included in the Net Amount (DMN) column of the warranty claim.

Your cooperation is greatly appreciated. Prompt return of the original engine will increase the effectiveness of this program.

If you have any questions regarding the exchange program administrative procedures, please contact the Product Quality Center

#### <u>Version History</u>

Version	2
	02/17/2020 - Created on.
odified	04/29/2020 - Updated to add 2021 Chevrolet Trailblazer.

















# GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.