



SIB 34 02 20

2020-04-20

NOTICEABLE JERK WHEN DRIVING OFF IN ACTIVE CRUISE CONTROL (ACC) MODE

MODEL

E-Series	Model Description	Production Date	Affected Option Code
G20	3 Series Sedan	July 1, 2019- February 28, 2020	With all-wheel drive and 05AU Active Driving Assistant Pro

SITUATION

A noticeable jerk can be felt at 2-3 mph when driving off in ACC mode.

CAUSE

Software in the Dynamic Stability Control (DSC) unit.

CORRECTION

Program the vehicle.

PROCEDURE

Determine the vehicle's current I-level by using AIR or the Key reader/ISPA NEXT application:

If the current vehicle I-level is below S18A-20-03-524, program the vehicle using ISTA 4.22.1x or higher (**released early March 2020**).

Model	Target integration level
G20 (3 Series Sedan)	S18A-20-03-524

If the current vehicle I-level is S18A-20-03-524 or higher, do not program the vehicle.

Run diagnosis with ISTA and work through any corresponding test module if necessary.

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply ([SI B04 23 10](#)).

For information on programming and coding with ISTA, refer to DealerSpeed / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

WARRANTY INFORMATION

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Update the vehicle to the required I-level or higher by performing and submitting for one of the open Technical Campaigns instead. Please be sure to also perform any additional work (before and/or after) the campaign repairs require and/or close the remaining open programming and encoding Technical Campaign repairs as outlined in the corresponding Service Information Bulletin.

Only if the above situation does not apply, the BMW software solution is then:

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program as described below.

Defect Code:	3452101400	Dynamic Stability Control - control unit temporary malfunction
Labor Operation	Description	Labor Allowance
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		
61 21 528	Connect an approved battery charger/power supply (indicated in AIR as Charging battery)	Refer to AIR
And:		
61 00 730	Programming/encoding control unit(s)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)

The programming procedure automatically reprograms and encodes all vehicle control modules which do not have the latest software I-level. If one or more control module failures occur during this programming procedure:

- Please claim this consequential control module-related repair work (including performing the IRAP Control Unit Recovery procedure first as required, refer to the SIB in AIR) under the defect code listed in this bulletin with the applicable AIR labor operations.

Please explain this additional work (The why and what) on the repair order and in the claim comments section

For control module failures that occurred prior to performing this programming procedure:

- When covered under an applicable limited warranty, claim the applicable test plan and the corresponding control module-related repair work using the applicable defect code and labor operations in AIR (including diagnosis with separate punch times).

Other Repairs

If other eligible and covered work is performed as a result of performing the ISTA diagnostics and related test plans, claim this work with the applicable defect code and the labor operations that are listed in AIR (including diagnosis with separate punch times).

