



## STAR ONLINE PUBLICATION

---

**Case Number:** S2023000020

**Release Date:** 04/01/2020

**Symptom/Vehicle Issue:** Tick Noise From A-pillar Front Power Top Side Rail

**Discussion:** If a tick or click noise is heard from the Sky One power roof system above the front row seat occupants heads see the below procedure to add anti-squeak tape.


**Parts Required:** MOPAR Anti-Squeak tape 05019054AA

1. Power the roof full open.
2. Remove the front four bolts on each side of the assembly (to loosen front of rail to body to gain access to Torx head fasteners between side rail and track)
  - a) Remove the front “blue” screws (#4 below) that secure the front of the power top assembly.
  - b) Remove the front “gold” screws (#2 below) at the front door openings.
  - c) Remove front two “red” screws in oval (#3 below)

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**

## STAR ONLINE PUBLICATION



1 – Rear Screws 70 mm (2.75 in) Screw Length

2 – Front Door Opening Screws 70 mm (2.75 in) Screw Length

3 – Middle Screws 103 mm (4 in) Screw Length

4 – Front Header Screws 20 mm (0.75 in) Screw Length


**NOTE:** The screws that anchor the power top assembly to the frame of the vehicle are different lengths. Damage can occur if a long screw is placed in a short hole. Refer to the illustration for proper screw locations.

3. Remove the front 2 Torx screws (1) between the track (3) and the SMC (composite sheet molded compound) side rail (2), repeat on the other side.


This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

## STAR ONLINE PUBLICATION



3. Obtain anti-squeak tape, service number 05019054AA, and cut out 9 through 12.




This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**

## STAR ONLINE PUBLICATION

---

4. Pry the black aluminum track up and position one piece of tape at the front and at the back of the of the T-nut hole, as shown in the photos below. Tip: apply tape to a blade and carefully slide into opening.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**

## STAR ONLINE PUBLICATION

---




5. Reinstall the 2 T-nut screws per side, torque to 14 Nm.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**

## STAR ONLINE PUBLICATION




6. Attach the front four bolts on each side of the assembly, torque all to 6 Nm.
  - a. Attach the front screw (#2 below) in the front door openings.
  - b. Attach the rear screw in the front door opening and the front screw in the rear door opening, two screws (#3 below).
  - c. Attach the screws (#4 below) that secure the front of the power top assembly.

Reinstall the front 4 screws

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found**

## STAR ONLINE PUBLICATION



1 – Rear Screws 70 mm (2.75 in) Screw Length

2 – Front Door Opening Screws 70 mm (2.75 in) Screw Length

3 – Middle Screws 103 mm (4 in) Screw Length

4 – Front Header Screws 20 mm (0.75 in) Screw Length

**NOTE:** The screws that anchor the power top assembly to the frame of the vehicle are different lengths. Damage can occur if a long screw is placed in a short hole. Refer to the illustration for proper screw locations.

7. Cycle the roof closed.

8. Road test to verify repair.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found