

Advanced Technical Information

Bulletin #: 2008

Part ID: 2048

Requested Filter Element Replacement in Connection with DMTL Replacement

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Panamera	2017 - 2020	971	N/A	N/A

Revision History

Revision	Release Date	Changes
0	May 12, 2020	Original document

Condition

A faulty tank leakage diagnosis module (DMTL) can trigger the malfunction indicator lamp (MIL) for numerous reasons, for example the DME fault "P245000 (002EB0) – Tank leakage diagnostic module, change-over valve – stuck open." In such instances, where the repair necessitates replacement of the DMTL, this ATI kindly requests replacement of the attached filter element shown below.

Technical Background

In addition to the analysis of faulty DMTL units, an associated analysis of the attached filter element is also necessary.

Page 1 of 2



Advanced Technical Information

Bulletin #: 2008

Part ID: 2048

2

Service Information

In the same PQIS entry and warranty request to replace the DMTL to properly repair the vehicle, please replace the filter element (Part 5) shown below. (Only 1 "repair kit for the evaporative emission canister" 9P1 898 209 is necessary.)




Figure 1 - Filter element requested for replacement with the DMTL

Warranty

As always, please document the repair completely in PQIS. For this repair, please code the "cause" as follows:

Cause location: 20480 Leakage diagnosis module

Cause symptom: 4045 Warning activated

Use the following troubleshooting labor operation: Please use the labor operation(s) already employed to replace the leakage diagnosis module.

20481950 Leakage diagnosis module remove and reinstall

Search Items

DMTL, tank leakage diagnosis module, DME, G2, P245000, EVAP, MIL

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.