ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.





SERVICE BULLETIN

APPLICABILITY: 2019-20MY Forester **NUMBER:** 12-291-20

SUBJECT:

Staining on Finish of Rear Gate Panel

DATE: 05/19/20

INTRODUCTION:

This bulletin announces a design change made to the rubber protector located between the top edge of the rear gate garnish and the glass. The change was made in response to a number of concerns regarding vertical brownish-colored stains appearing on the rear gate panel below the garnish and / or the license plate as shown below. Although hard to see in the photos, the callouts represent locations where the staining has been identified.





The staining is caused by an anti-hardening chemical used in the rear wiper blade insert. Over time, the chemical may be extracted from the insert by vehicle washing and rainwater. Carried by the runoff water, the chemical can drain through the gaps between the sections of the old-style rubber protector which may cause a stain to develop on the rear gate finish below the garnish. Depending on the vehicle trim level, new style protectors either eliminate or reduce the number of gaps from 4 to 2, redirecting the runoff water. Detailed illustrations are provided below in the Parts section.

PRODUCTION CHANGE INFORMATION:

The new-style protectors were incorporated into production starting with VIN LH546087.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

Bulletin Number: 12-291-20; Date: 05/19/20


PART INFORMATION:

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.

NOTES:

- For purposes of this bulletin, Base and Premium trim level vehicles are **Standard** models.
- Sport, Limited and Touring trim level vehicles are **High-Grade** models.

In the illustrations below, the protector is shown as the red line along the top edge of the rear gate garnish.




NEW			Interchangeability	Old			Model /
Part Number	Part Name	Qty. Req'd.	*(1)	Part Number	Part Name	Qty. Req'd.	Grade
91713SJ060	PROTECTOR UPR STD	1		91713SJ000	PROTECTOR- REAR GARNISH	2	Standard
91713SJ090	PROTECTOR UPR RH	1	New Part to Old Vehicle: Yes .	91713SJ010	PROTECTOR- REAR GARNISH A	2	Model
91713SJ070	PROTECTOR UPR HG	1	Old Part to New Vehicle: <u>No</u> .	91713SJ000	PROTECTOR- REAR GARNISH	2	High- Grade Model
				91713SJ020	PROTECTOR- REAR GARNISH A	2	

ADDITIONAL NOTES:

Both upper protectors described above (which replace #5 shown in the illustrations below) along with the multiple-piece lower protectors which are assembled along the bottom edge of the garnish (#8 below) and the left and right-hand garnish brackets (#1 and #4 below) are all **one-time use** items requiring replacement any time the rear gate garnish is removed. (The SUBARU emblem (#10) is also one-time use.) Garnish retaining clip reference is also provided below although, they are reusable as long as they are not damaged.

Use the exploded view illustrations supplied below for reference when ordering.



SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedures for replacing the protector remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time, every time. This includes but is not limited to: important SAFETY precautions, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code	
TRUNK/REAR GATE PANEL GARNISH, R&R	B916-281	0.5	XDT-43	

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 12-291-20; Date: 05/19/20 Page 4 of 4