

GROUP	NUMBER	
FUEL SYSTEM	20-FL-003H	
DATE	MODEL(S)	
MAY, 2020	SONATA HYBRID (LF HEV)	

Description:

Certain 2016-2019 Sonata Hybrid (LF HEV) vehicles may experience check engine light illumination with DTC P0456 - Evaporative System (EVAP) - Very Small Leak stored.

Salt particulate deposit can form inside the Natural Vacuum Leak Detection (NVLD) sensor which may cause intermittent operation prompting the DTC P0456 and check engine light.

This bulletin provides the procedure to replace the NVLD sensor with an updated Air Filter Kit to help prevent entry of the salt particulates.

Applicable Vehicles: Certain 2016-2019 Sonata Hybrid (LF HEV)

Parts Information:

Part Number	art Number Description		Remarks	
31450-E6501FFF	 AIR FILTER KIT Vent pipe, mounting brackets and hoses assembly Filter with inlet hose Band strap 		All vehicles	
31480-4R100FFF	NVLD Pressure Sensor Assembly		All vehicles	
00232-19035	UNDERCOATING AEROSOL (Non-Rubberized Type)		One canister can be applied to 10 vehicles	

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal P/N	Nature Code	Cause Code
SONATA HYBRID (LF HEV)	31450F02	AIR FILTER KIT & NVLD REPLACEMENT	1.3 M/H	31480-4R100FFF	I3A	ZZ3

NOTE: \$1.23 will be reimbursed in sublet under labor op 31450F2 for undercoating aerosol application.


Service Procedure:

A. AIR FILTER KIT REPLACEMENT


1. Open the fuel filler door and loosen the filler neck mounting bolts (A).



2. Lift up the vehicle and remove the left rear tire & wheel assembly (B).



3. Remove the left rear wheel guard (C).




TSB #: 20-FL-003H Page 2 of 8


4. Release the hose clamp and disconnect the upper hose (D).

Disconnect the Canister Close Valve (CCV) connector (E).

Loosen the air filter mounting bolts (F).



5. Release the hose clamp.
Disconnect the lower hose (G) and air filter from the vent line.



NOTICE

Utilize a ratcheting wrench type or low profile ratchet and socket combo where mounting bolts accessibility is limited.

Scrub off the undercoating material from the bolt heads and threads for ease of loosening bolts.


TSB #: 20-FL-003H Page 3 of 8

6. Loosen the upper vent line bracket clamping bolt (H).

Note: Mounting bolt head is facing towards the body.




7. Release the hose clamp and disconnect the ventilation hose (I) from the Nature Vacuum Leak Detection (NVLD) valve.



8. Loosen the lower vent line bracket mounting bolt (J).

Then pull away the lines slightly and loosen the clamping bracket bolt (K).



TSB #: 20-FL-003H Page 4 of 8


9. Remove the filler neck vent line, upper hose and air filter.



B. NVLD REPLACEMENT

10. Disconnect the NVLD connector (L).


Release the hose clamp and disconnect the vent hoses (M).



11. Loosen the NVLD mounting bolts (N) and remove the NVLD.

Tightening Torque : 2.3 ~ 3.3 N.m (0.2 ~ 0.3 kgf.m, 1.7 ~ 2.5 lb-ft)

Install the new NVLD and reinstall the removed parts in reverse order of removal.



TSB #: 20-FL-003H Page 5 of 8

12.

NOTICE

Require to separate and reuse the CCV which is part of the removed air filter.

Lift up the locking lever, rotate CCV 30 degrees and then pull away to release the CCV.




13. Install the new air filter KIT and reinstall the removed parts, including CCV, in reverse order of removal.




NOTICE

Follow markings to ensure vent pipes and brackets are aligned properly.



TSB #: 20-FL-003H Page 6 of 8

14. Spray the black undercoating aerosol evenly to each vent line bracket for approximately 10 seconds.



15. After spaying, tie the CCV wiring and vent pipe using band strap.





TSB #: 20-FL-003H Page 7 of 8

C. GDS Evap Leakage Test:

Follow GDS instructions and perform GDS Evap Leakage Test to confirm parts and hoses are installed properly.

16.





17. Check for installed parts and hose connections if EVAP leakage is detected.

After making corrections, clear the DTC(s) and perform GDS Evap Leakage Test again.

Repair procedure is completed if EVAP Leakage Test doesn't detect any leakage.

TSB #: 20-FL-003H Page 8 of 8