



Technical Service Bulletin

43 Dynamic Ride Control (DRC): assessment of leaks

43 20 40 2059842/1 June 18, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS6, RS7,	2013 - 2021	All	Dynamic Ride Control
RS5, RS5, Cabriolet	2013 - 2017	All	Dynamic Ride Control
RS4	2013 – 2015, 2017 -2021	All	Dynamic Ride Control

Condition

Customer states:

- Noises from the suspension.
- There is an oil film on the shock absorbers.



Note:

This information is specifically for the shock absorber of the Dynamic Ride Control (DRC) system PR Code 2MC.

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

1. An oil film running down a shock absorber indicates that it leaks. The shock absorber must only be replaced if this leak can be clearly assigned to it, as shown in the picture. (Figure 1)



Figure 1. DRC shock absorber with clear oil loss.

2. A minor oil film and a resulting dirt build-up are no indication of a leak. They result from oil residues during the installation or caused by "sweating" of the shock absorber.

There is no restriction in the function of the shock absorber. Tests with such components show that the shock absorbers are in perfect working order.

Do not replace any component.

The following illustrations show examples of non-leaking or "sweating" shock absorbers (Figure 2 - 4).





Technical Service Bulletin



Figure 2, 3, and 4. Oil marks/residues in the wheel housing/shock absorber.

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	4090/4293		
Damage Code:	0050		
Labor Operations:	Replace shock absorber front	4090 5550 Or 4090 1950	See SRT with associated operations
	Replace shock absorbers front	4090 5650 Or 4090 2050	See SRT with associated operations
	Replace shock absorber rear	4293 5550	See SRT with associated operations
	Replace shock absorbers rear	4293 5650	See SRT with associated operations



Technical Service Bulletin

Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2059842/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Shock absorber front	01 or 02
See ETKA	Shock absorber rear	01 or 02

Additional Information

All part and service references provided in this TSB (2059842) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.