



Technical Service Bulletin

94 Cornering lights stay on after the ignition is turned off

94 20 27 2059861/1 June 17, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019 - 2020	All	LED headlamps

Condition

Customer states:

- After they shut the ignition off, the cornering lights remain on.

Workshop findings:

- The customer concern is able to be duplicated.
- No DTC is stored.

Technical Background

The cornering lights will switch off after the start of bus silence (sleep cycle).

Production Solution

New Target Data Container (ZDC) in left and right headlight light control module 2, A31/A27 (address word 00D6/00D7) addressed the condition.

Service

SVM Update Instructions

1. Perform the replacement test plan for address word 00D6. This is necessary to temporarily save the light classification (BCI codes) of both headlights.
2. Continue as if replacing the control module with the old module still installed.
3. When prompted, use the selection that an SVM code exists. Enter SVM code D6A007.
4. The test program then writes the temporarily saved light classes of both headlights back into the control modules at the end of the update procedure.



Technical Service Bulletin

Diagnostic Address	Old Target Data Container Number	Old ZDC Version	New Target Data Container Number (or higher)	SVM Code Input
00D6	83A909471D	*	83A909471E	D6A007
00D7	83A909472D	*	83A909471E	

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9407		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2059861/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2059861) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property



Technical Service Bulletin

rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.