



Technical Service Bulletin

17 Oil minimum warning, the oil level is found low with the dipstick tool

17 20 05 2059366/4 June 30, 2020. Supersedes Technical Service Bulletin Group 17 number 20-04 dated June 30, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8, S8	2019 - 2020	All	4.0T

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised <i>Warranty</i> (Updated Service Number)
3	06/30/2020	Revised <i>Required Parts and Tools</i> (Removed Parts table)
2	05/18/2020	Revised header (Added vehicles)

Customer states:

- The message "Oil minimum warning, add one quart of oil" appears in the instrument cluster.

Workshop findings:

- When measured with the special tool T40178B, the oil level is found to be below the minimum level.
- The oil level is not above the maximum level (when measured with the special tool T40178B).
- There are no DTCs related to the oil level stored in the ECM memory.

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

1. Use special tool T40178 to verify that the oil level is below the minimum level (please provide/record the oil level in the claim description section):
 - Adjust the tool according to Elsa (Figure 1).
 - The oil level needs to be below “0” (minimum).




Figure 1. Adjusting the tool.

2. Using ODIS, record the measured values shown in Figure 2. Save the log and upload it to GFF Paperless.



Note:

For all warranty repairs, the complete list of measured values as shown in Figure 2 needs to be uploaded to GFF paperless for warranty claim payment. Failure to do so will result in non-payment of the claim.

MVB ID	MVB description	MVB ID	MVB description	MVB ID	MVB description
1	IDE00151 Engine oil level	11	IDE10065 Engine_oil_level_history_2	21	IDE10582 Engine_oil_level_test_procedure_3
2	IDE00196 Engine oil temperature	12	IDE10066 Engine_oil_level_history_3	22	IDE10732 Engine_oil_level_volume_factor
3	IDE02756 Number_Of_Engine_Start_Manuell	13	IDE10067 Engine_oil_level_history_4	23	IDE11267 Oil_level_measurement_maximum_value_percent
4	IDE02757 Number_Of_Engine_Start_Automatic	14	IDE10068 Engine_oil_level_history_5	24	IDE11268 Oil_level_measurement_minimum_value_percent
5	IDE04820 Fuel_percentage_by_vaporisation_from_engine_oil	15	IDE10069 Engine_oil_level_history_6	25	IDE11302 Engine_oil_level_test_procedure_1_qualification
6	IDE06570 Oil_level_and_oil_temperature_sensor_sump_temperature	16	IDE10070 Engine_oil_level_history_7	26	IDE11303 Engine_oil_level_test_procedure_3_qualification
7	IDE09529 Fuel_mass_flow_degassing_from_engine_oil	17	IDE10071 Engine_oil_level_history_8	27	IDE12748 Oil_level_measurement_refill_quantity
8	IDE09531 Fuel_mass_in_engine_oil	18	IDE10072 Engine_oil_level_history_9	28	IDE14152 Oil_level_measurement_compensated_maximum_value
9	IDE10063 Engine_oil_level_actual_value	19	IDE10580 Engine_oil_level_test_procedure_1	29	IDE14153 Oil_level_measurement_compensated_minimum_value
10	IDE10064 Engine_oil_level_history_1	20	IDE10581 Engine_oil_level_test_procedure_2		

Figure 2. Measured values to record in GFF using ODIS.

3. Please start the engine oil consumption test part 1 according to ODIS.
4. When the vehicle comes back for the oil consumption test part 2, please repeat step 1 and step 2 first.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1716		
Damage Code:	0010		
Labor Operations:	Dipstick check	1716 0199	60 TU
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 30 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2059366/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool number	Tool Description
T40178B	Oil level measuring tool

Additional Information

All parts and service references provided in this TSB (2059366) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in



Technical Service Bulletin

any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.