

Technical product information

Topic	Creaking noise from the front suspension when manoeuvring
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2048616/7
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
running gear -> shock absorber/suspension control -> jounce	noise, vibration -> creak	front

New workshop code

Object of complaint	Complaint type	Position
running gear -> running gear, springs, shock absorbers -> axle member mount	noise, vibration -> noise	left
running gear -> running gear, springs, shock absorbers -> axle member mount	noise, vibration -> noise	right

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	E		*	*	*
4V1*	2018	E		*	*	*
4V1*	2019	E		*	*	*
4V1*	2020	E		*	*	*

Documents

Document name
master.xml
creaklowersuspensionleverbush.docx
kovomoanddiesel.docx
lowersuspensionleverw12only.docx
transmissionmountsfront.docx

Customer statement / workshop findings

Creaking noise from the front suspension when manoeuvring

Technical background

Verify that the customer complaint matches the sound file within the Bentley Hub – Reference TPI Transaction number 2048616/-

TIP: When listening to the sound file the noise can be heard from between 0 and 3 seconds

The noise present in the sound file is caused by defective Lower suspension lever - Rear - Hydraulic mounts. In order to reproduce the noise this bush must be twisted, therefore the noise can appear in the following circumstances

- When performing parking manoeuvres with the brake applied
- When steering from lock to lock with the vehicle in motion and the brake applied
- When the vehicle is moved with steering input over uneven surfaces (for e.g. a ramp or speed bump)

If the customer complaint occurs in any of the above circumstances and the noise can be clearly assigned to the noise within the sound file – Refer to the instructions within the Measure section of this TPI

Production change

*

Measure

1) Replace the right hand front and left hand front rearmost lower suspension lever inner hydraulic mounts - Refer to Repair manual Rep. Gr. 40 front suspension, lower suspension lever bushes – to remove and fit NOTE: Should the remove and refit instructions not be visible within the Repair manual please refer to the attached documents, please ensure the correct document is followed as the remove and refit procedures for the front rearmost lower suspension levers removal is different depending on type of engine which is fitted

NOTE: The lubricant quoted within the procedure should be sourced locally or use a suitable alternative of the same specification

Figure 1 shows for example the left hand front rearmost lower suspension lever (A) the hydraulic mount which must be changed is located at (B)

NOTE: Ensure the right and left hand side hydraulic mounts are replaced

Within the Repair manual procedure there are single use items which must be replaced and not reused. Ensure that new replacements are available prior to starting this procedure – Refer to Elsa pro and ETKA parts catalogue




Figure 1

Warranty accounting instructions

Warranty type 110 or 910

Damage Service Number 40 20

Damage Code 00 20

Bentayga W12

Labour Operation Code 40 20 56 00

Time 590 TU

Bentayga Kovomo V8

Labour Operation Code 40 20 56 20

Time 260 TU

Bentayga Diesel

Labour Operation Code 40 20 56 40

Time 270 TU

Parts information

Part number	Description	Quantity
Refer to ETKA parts catalogue	Hydraulic mounts	2