

10. Wait until the vehicle is communicating with DT II.
11. Go to:
 - a. **Vehicle Setup > BCM Customization**
12. In the TCU line:
 - a. Click drop-down menu.
 - b. Select: **Not Installed**
13. Click:
 - a. **Update Vehicle > OK**
14. Cycle ignition.
15. Start engine.
16. Did engine start?
 - a. **Yes:** Deactivation and removal is complete, go to step 17.
 - b. **No:** Repeat the TCU Deactivation and Removal Procedure .
17. Turn IGN OFF.
18. Remove DT II.

Credit Procedure

NOTE

Enter bulletin number into comment section of claim.

Verify that vehicle is under warranty.

Submit a warranty claim per Table 4 for all TCUs removed and dust caps installed.

Table 4.

ITEM	DATA
Claim Type	MC/Standard Claim or PRD/PDI claim
Problem Part Number	41000645 or 41000721
Quantity	Leave Blank
Labor Code	6195
Time	0.5–0.6 h Depending on the model
Customer Concern Code	9203
Condition Code	3109
Replacement Part No.	69202412
Quantity	1

Return Parts

Hold all claimed parts for 60 d from date of credit issued for possible field inspection and/or request to return to factory. After 60 d, destroy and discard the parts.