

# Service Update

## N202294740 Software Update for Multiple Modules



**Release Date:** June 2020

**Revision:** 00

**Attention:** This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

| Make     | Model | Model Year |      | RPO | Description |
|----------|-------|------------|------|-----|-------------|
|          |       | From       | To   |     |             |
| Cadillac | CT5   | 2020       | 2020 |     |             |

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

|                   |   |
|-------------------|---|
| <b>Condition</b>  | Certain 2020 model year Cadillac CT5 vehicles may require individual software updates to multiple modules to address various minor issues such as steering feel and data communication. |
| <b>Correction</b> | Dealers are to reprogram multiple modules.  |

### Parts

No parts are required for this repair.

### Warranty Information

| Labor Operation | Description                                     | Labor Time | Trans. Type | Net Item |
|-----------------|---|------------|-------------|----------|
| 9105124*        | Sequential Module Reprogramming with SPS or TLC | 0.5        | ZFAT        | N/A      |

\* **Important:** To avoid warranty transaction rejections, carefully read and follow the instructions below:

- The SPS Warranty Claim Code must be accurately entered in the "SPS Warranty Claim Code" field of the transaction.
- When more than one Warranty Claim Code is generated for a programming event, it is required to document all Warranty Claim Codes in the "Correction" field on the job card. Dealers must also enter one of the codes in the "SPS Warranty Claim Code" field of the transaction, otherwise the transaction will reject. It is best practice to enter the FINAL code provided by SPS.

### Warranty Claim Code Information Retrieval

If the SPS Warranty Claim Code was not recorded on the Job Card, the code can be retrieved in the SPS system as follows:

- Open TIS on the computer used to program the vehicle.
- Select and start SPS.
- Select Settings.
- Select the Warranty Claim Code tab.

The VIN, Warranty Claim Code and Date/Time will be listed on a roster of recent programming events. If the code is retrievable, dealers should resubmit the transaction making sure to include the code in the SPS Warranty Claim Code field.

### Service Procedure

**Note:** Carefully read and follow the instructions below.

- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to [www.gmdesolutions.com](http://www.gmdesolutions.com) for further information. If not available, connect a fully charged 12V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Turn OFF or disable systems that may put a load on the vehicles battery such as; interior lights, exterior lights (including daytime running lights), HVAC, etc.

# Service Update

## N202294740 Software Update for Multiple Modules



- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.

**Important:** No setups are required for this sequential programming field action.

Service Programming System

Supported Controllers

Select Controller

|       |  |
|-------|--|
| Z4    | Vehicle wide Capture of Module Identification Data           |
| T3    | Audio Amplifier  |
| K9    | Body Control Module  |
| K160  | Brake System Control Module                                  |
| K20   | Engine Control Module  |
| B174W | Frontview Camera Module                                      |
| K212  | Gear Shift Control Module                                    |
| A26   | Heater and Air Conditioning User Interface Control - Front   |
| Z1    | Immobilizer Learn  |
| S165  | Infotainment Control Switch                                  |
| P16   | Instrument Panel Cluster Control Module                      |
| K210  | Image Processing Module                                      |
| PFA   | Multimodule Coordinated Sequence - Bulletin N202294740       |
| K73   | Power Steering Control Module                                |
| A11   | Radio  |
| A22   | Radio Control  |
| K38   | Restraints Control Module                                    |
| K85P  | Restraints Occupant Classification System Module - Passenger |
| K56   | Serial Data Gateway Module                                   |
| K73   | Telematic Control Module                                     |
| K71   | Transmission Control Module                                  |

Select Function / Sequence

Programming

Select Programming Type

Normal

VCI

Print ECU Data Next > Cancel

5618437

Techline Connect  
Version: 1.5.0 Production

1G6DT5RK1L0100075  
2020 • Cadillac • CT5

Connect Vehicle

DASHBOARD GDS2 SI SPS2 Support RPO Search Service Manuals

SPS2

Supported Controllers

| Code  | Controller Name  |
|-------|--|
| Z4    | Vehicle wide Capture of Module Identification Data           |
| T3    | Audio Amplifier  |
| K9    | Body Control Module  |
| K160  | Brake System Control Module                                  |
| K60   | Column Lock Module   |
| K40D  | Driver Seat Adjuster Memory Module                           |
| K20   | Engine Control Module  |
| B233B | Forward Range Radar Sensor - Long Range                      |
| B174W | Front View Camera - Windshield                               |
| K212  | Gear Shift Control Module                                    |
| A26   | Heater and Air Conditioning User Interface Control - Front   |
| K210  | Image Processing Module                                      |
| PFA   | Multimodule Coordinated Sequence - Bulletin N202294740       |
| K73   | Power Steering Control Module                                |
| A11   | Radio  |
| A22   | Radio Control  |
| K38   | Restraints Control Module                                    |
| K85P  | Restraints Occupant Classification System Module - Passenger |
| K56   | Serial Data Gateway Module                                   |
| K73   | Telematic Control Module                                     |
| K71   | Transmission Control Module                                  |

Select Function Sequence

Programming

Select Programming Type


Normal

VCI

5618444


# Service Update

## N202294740 Software Update for Multiple Modules



5618445


1. Reprogram the sequential multiple modules through SPS/Techline Connect (SPS and Techline Connect screens shown) by selecting “ZFA - Multimodule Coordinated Sequence-Bulletin N202294740” on the select controller screen as shown. Select “Next” and follow all onscreen instructions.



5431209

# Service Update

## N202294740 Software Update for Multiple Modules



5618451

**Important:** SPS and Techline Connect screen shown.

**Important:** To avoid warranty transaction rejections, you **MUST** record the warranty claim code provided on the SPS and Techline Connect Warranty Claim Code (WCC) screen on the job card. Refer to callout (1) above for the location of the WCC on the SPS and Techline Connect screen.

- Record SPS Warranty Claim Code on job card for warranty transaction submission.

### Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support  
Voluntary Technician  
Certification**

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5431  
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 15, 2020

Subject: N202294740 - Service Update  
Software Update for Multiple Modules

Models: 2020 Cadillac CT5

To: All General Motors Dealers

General Motors is releasing Service Update N202294740 today. The total number of U.S. vehicles involved is approximately 6,403. Please see the attached bulletin for details.

**Global Warranty Management (GWM)**

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated June 16, 2020 or sooner. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS