

WLE6 Workshop campaign - Replacing pulse sender

Version 1

WLE6 Workshop campaign with customer letter - Replacing pulse sender

Overview

Due to a manufacturing problem with the pulse sender for the crankshaft, there is a possibility that the crankshaft speed signal and crankshaft position signal may be lost at times on the affected vehicles.

If this happens, it may take longer for the engine to start and the warning message "Engine control fault" may be displayed in the instrument cluster.

To prevent this from happening, the pulse sender must be replaced on the affected vehicles.

| | |
|-------------------|---------------|
| Model type | Cayenne (92A) |
| Model year | 2017 - 2018 |
| Number | 1,900 |

Parts required

| Part No. | Designation | Quantity/vehicle | Parts return* |
|-----------------|--------------------|-------------------------|----------------------|
| V04015001U | Pulse sender | 1 ea. | No |

* The parts must be stored until such a time as the **related warranty or campaign claim has been credited**. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

An initial small quantity auto-allocation has been shipped for repairs to begin. Please order additional parts as needed, based on vehicles that arrive with this open campaign.

Warranty processing

Validity:

This workshop campaign will be carried out up to 6/15/2025 and will be closed by the specified date.

Please note that warranty claims can only be processed before this date.

Scope 1:

| | |
|-------------|-------------|
| Damage code | WLE6 66 000 |
| Repair code | 2 |

Working time

97 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

Work instruction

TI No. 69/20, Group 2, Service, WLE6

Vehicle list and allocation

See PCSS or attached list for reference

Technical Information*

See PCSS or attached TI for reference

* Please find attached the Technical Information as a PDF file. Please bear in mind that this is provided for your information only. The version published in PCSS is the definitive version.

[92A 2 69-20 WLE6 - Replacing Pulse Sender](#)[\(Workshop Campaign\).pdf](#)**27.3 KB**

(34 views)

[WLE6 VIN List.xlsx](#)**45.4 KB**

(32 views)

Created by [Ryan Cooney](#) on Jul 31, 2020 10:38 PM. Last modified by [Ryan Cooney](#) on Aug 3, 2020 4:01 PM.

Categories: Workshop Campaigns, Cayenne

Tags : [92a](#), [workshop campaign](#), [year_j](#), [wle6](#)

409 Views

[Report Abuse](#)

| Content and Topics | Personal | Manage | Create |
|--------------------|-------------------|---------------------|-----------------|
| Your Groups > | Edit Profile > | Admin Console > | Discussion > |
| Your Content > | Change Password > | PPN Administration> | Files > |
| Your Places > | | | Document > |
| | | | Collaboration > |
| | | | Document |
| | | | Blog Post > |
| | | | Poll > |
| | | | Event > |
| | | | Photo Album > |
| | | | Idea > |
| | | | Space > |
| | | | Group > |

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice.](#) [Copyright.](#) [Terms of use.](#) [Privacy Policy.](#) [Cookie Policy.](#) [009](#)