

Technical product information

Topic	Transmission communication DTC's (Numerous)
Market area	Bentley: worldwide (2WBE)
Brand	Bentley
Transaction No.	2059068/2
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
vehicle service -> vehicle diagnosis -> guided fault finding	control units, services -> with event log entry	
electrical power, electric system, data transfer -> data bus systems	component / consumables	
power transmission -> power distribution, power flow -> power flow	functionality -> without function / defect	
electrical power, electric system, data transfer -> power supply	functionality	

Vehicle data

New Continental GT and New Continental GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S*	2018	E		*	*	*
3S*	2019	E		*	*	*
3S*	2020	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Customer statement

Drive system fault active on DIP (Figure 1)



Figure 1

Workshop findings

Various/numerous Transmission control module (TCM) communication DTC's logged

Technical background

Loose pins within the transmission link harness to the Mechatronic unit for dual clutch gearbox -J743- connections can lead to communication based DTC's

Production change

Not applicable

Measure

-
- Ensure the ignition is switched off for the duration of this procedure
- 1) Remove the left hand front wheel arch liner - Refer to Repair manual Rep.Gr 66
- 2) Gain access and disconnect the transmission control module plug T58g - Refer to Repair manual Rep.Gr 37
 - Referring to Figure 2 and the applicable current flow diagram - Disconnect the three connections
- 3) Once disconnected carry out pin/terminal grab checks on all male and female connections (All three connections)




Figure 2

- 4) Remove the rear subframe support – Rep.Gr 40 (Figure 3)



Figure 3

5) Disconnect the connections (Figure 4 - Arrows) from the Mechatronic unit for dual clutch gearbox -J743-

Referring to the applicable current flow diagram and Figure 5 and 6- Carry out resistance and pin/terminal grab checks on all disconnected connections from the T58g connector to T20ch and T20ci on the harness.



Figure 4

Check T58g to connector T20ci

Connector T58g		Connector T20ci	Resistance
PIN 1	∞	PIN 4	0.4
PIN 3	∞	PIN 2	0.2
PIN 4	∞	PIN 3	0.5
PIN 6	∞	PIN 1	0.4
PIN 9	∞	PIN 8	0.4
PIN 10	∞	PIN 6	0.1
PIN 11	∞	PIN 10	0.3
PIN 12	∞	PIN 20	0.3
PIN 13	∞	PIN 13	0.5
PIN 16	∞	PIN 17	0.4
PIN 22	∞	PIN 5	0.4
PIN 23	∞	PIN 7	0.4
PIN 24	∞	PIN 9	0.4
PIN 25	∞	PIN 11	0.4
PIN 26	∞	PIN 12	0.4
PIN 27	∞	PIN 14	0.4
PIN 29	∞	PIN 16	0.5





Figure 5

Connector T58g	Connector T20ch	Resistance
PIN 1	to PIN 5	0.4
PIN 14	to PIN 1	0.4
PIN 21	to PIN 20	0.4
PIN 34	to PIN 18	0.3
PIN 36	to PIN 3	0.3
PIN 37	to PIN 2	0.4
PIN 38	to PIN 4	0.4
PIN 41	to PIN 9	0.4
PIN 42	to PIN 13	0.5
PIN 43	to PIN 10	0.4
PIN 44	to PIN 15	0.4
PIN 46	to PIN 17	0.4
PIN 48	to PIN 19	0.5
PIN 49	to PIN 16	0.4
PIN 50	to PIN 6	0.4
PIN 51	to PIN 7	0.4
PIN 52	to PIN 8	0.4
PIN 54	to PIN 11	0.4
PIN 56	to PIN 12	0.4
PIN 58	to PIN 14	0.4



Connector T20ci	Resistance
PIN 1	to PIN 5 5.1
PIN 1	to PIN 7 5.3
PIN 2	to PIN 6 5.2
PIN 2	to PIN 20 5.3
PIN 3	to PIN 8 5.3
PIN 3	to PIN 9 5.3
PIN 3	to PIN 10 5.3
PIN 3	to PIN 12 10.9
PIN 3	to PIN 13 1.1
PIN 3	to PIN 14 1.1
PIN 4	to PIN 11 5.3
PIN 16	to PIN 17 1800

Connector T58g	Power supply	Resistance
PIN 2	to Ground	0.2
PIN 5	to Fuse box 5K 20A	0.2
PIN 55	to TV48	0.3

Figure 6

6) Should any issues be found on either end of the link harness, the link harness should be replaced.

Should any issues be found with the Mechatronic unit for dual clutch gearbox -J743- pin connections or the transmission control module plug (T58g) pin connections

Or

The male connections of the plugs shown in Figure 2

Please raise a DISS query and await feedback before carrying out any further work

Warranty accounting instructions

Warranty type: 910 or 110

Service ID number: 9797

Damage type: 0040

Labour

Time to conduct wiring checks

Labour operation code: 38850105

Time: 160 Time units

Time to replace link harness

Labour operation code: 38855555

Time: 20 Time units

Parts information

Part number	Description	Quantity
971 971 771	Link harness	1