



SERVICE BULLETIN

| | | |
|------------------------------|--------------------------|-----------------------|
| Classification: EL20-009a | Reference: NTB20-029a | Date: July 6, 2020 |
|------------------------------|--------------------------|-----------------------|

2020 TITAN AND TITAN XD; TELEMATICS (IVC) SERVICE INFORMATION

APPLIED VEHICLES: 2020 Titan and Titan XD (A61)

APPLIED TRIM: SV, SL, Platinum Reserve, and PRO-4X

SERVICE INFORMATION

The vehicles listed under **APPLIED VEHICLES** that come equipped with a factory installed SOS switch, located near the overhead map lamp, also come equipped with a wireless communication device called a Telematics Communication Unit (TCU). With an active NissanConnect Services™ subscription, the TCU communicates with the Nissan Data Center to provide various security and convenience services.

This bulletin contains important service procedures that must be performed properly in order to set up and maintain the telematics/in-vehicle communications (IVC) system for the vehicles listed under **APPLIED VEHICLES**.

- A table has been provided, on the next page, that lists the steps required to successfully configure a TCU after it has been replaced.
- A check-off sheet has been provided in this bulletin to print and check off steps as they are completed. **Staple the completed check-off sheet to the repair order.**

Nissan bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

REQUIRED ACTIONS

IMPORTANT: After TCU replacement (steps 1-12):

- If all of the steps in this bulletin are not completed, telematics services will not operate properly.
- Follow all of the steps in this bulletin and use the check-off sheet provided on page 13.
- If the TCU is replaced and the steps are not followed, the warranty claim will be denied.

| ORDER OF COMPLETION | 1ST | 2ND | 3RD |
|---------------------|---------------|-----------|---------------------------|
| | CONFIGURE TCU | WRITE VIN | REGISTER INTELLIGENT KEYS |
| | ✓ | ✓ | ✓ |

TCU REPLACEMENT

NOTICE

To avoid damage to the vehicle, only install new, unused TCUs into a vehicle. Each TCU is registered to a specific VIN and will not function if swapped into another vehicle.

IMPORTANT:

- During this procedure, Intelligent Key registration must be performed. You **MUST** have ALL customer Intelligent Keys collected.
- The new/replacement TCU must come from Nissan North America parts supply.
- TCU configuration is required after replacement. Refer to step 13 on page 7.

NOTICE

Configuration must be done prior to performing Write VIN. If Write VIN is performed prior to configuration, the TCU may not function properly and might need replacement.

NOTE: The warranty claim will be denied if this is not followed correctly.

NOTICE

Perform the following before saving the VIN data and configuration to prevent damage to the TCU.

- Connect the AC Adapter to the CONSULT PC.
- Connect the CONSULT PC to the Internet via Wi-Fi or a network cable.
- Ensure ASIST on the CONSULT PC has been synchronized (updated) to the current date and all C-III plus software updates (if any) have been installed.
- Turn OFF all external Bluetooth® devices (e.g., cell phones, printers, etc.) within range of the CONSULT PC and the plus VI. If Bluetooth® signal waves are within range of the CONSULT PC or plus VI during reprogramming, the reprogramming may be interrupted.
- Turn OFF all vehicle electrical loads.
- Turn ON the hazard warning lamps.
- Connect a battery maintainer or smart charger, set to reflash mode or a similar setting, to ensure the battery voltage stays between 12.0 V and 15.5 V.

Save VIN Data from Original TCU

1. Set the parking brake.
2. Connect C-III plus and the plus VI to the vehicle.
3. Turn the ignition ON with the engine OFF.
4. Launch C-III plus on the CONSULT PC.

5. Select **Diagnosis (One System)**.




Figure 1

6. Select **IVC**.

NOTE: If the VIN data cannot be saved, proceed to step 11 on page 6. You will be instructed to manually enter the VIN at step 40 on page 14.




Figure 2

7. Select **Work Support**.




Figure 3

8. Select **SAVE VIN DATA**, and then select **Start**.




Figure 4

9. Select **Start**.

NOTE: If the VIN data cannot be saved, proceed to step 11 on page 6. You will be instructed to manually enter the VIN at step 40 on page 14.




Figure 5

10. Select **End**.




Figure 6

Remove the Original TCU

11. Remove the TCU from the vehicle.

- Refer to the ESM for removal information: **DRIVER INFORMATION & MULTIMEDIA > AUDIO VISUAL & NAVIGATION SYSTEM > REMOVAL AND INSTALLATION > TCU.**

Install the New TCU

NOTICE

Configuration must be done prior to performing Write VIN. If Write VIN is performed prior to configuration, the TCU may not function properly and might need replacement.

NOTE: The warranty claim will be denied if this is not followed correctly.

12. Install the new / replacement TCU into the vehicle.

- Refer to the ESM for installation information: **DRIVER INFORMATION & MULTIMEDIA > AUDIO VISUAL & NAVIGATION SYSTEM > REMOVAL AND INSTALLATION > TCU.**

Configure the TCU

13. Select **Re/programming, Configuration**.
NOTE: C-III plus screens for steps 14-16 are not shown.
14. Read the precautions on the C-III plus screen, and then select **Next**.
15. Select the model and model year.
16. Select **Select**, and then select **Confirm**.




Figure 7

17. Select **IVC**.




Figure 8

18. Select **After ECU Replacement**.




Figure 9

19. Select **Manual selection**.




Figure 10

20. Select the applicable **Type ID**.

- For 2020 Titan (WITH Remote Engine Start): 28277-9FV0A
- For 2020 Titan (WITHOUT Remote Engine Start): 28277-9FV2A

NOTE: If C-III plus automatically selects the Type ID, there will be no options shown under **Type ID** (see Figure 11). Skip to step 22.




Figure 11

21. Select **Next** (not shown).

22. Select **OK**.

Write the VIN to the TCU

NOTICE

Configuration must be done prior to performing Write VIN. If Write VIN is performed prior to configuration, the TCU may not function properly and might need replacement.

NOTE: The warranty claim will be denied if this is not followed correctly.

23. Navigate to **IVC Work support**.
 - Refer to steps 1-7 on pages 4-5.

24. Select **WRITE VIN (SAVED DATA)**.

NOTE: If the VIN DATA could not be saved in step 9, proceed to **Manually Enter VIN Data (if needed)** at step 40 on page 14.

25. Select **Start**.




Figure 12

26. Select **Start**.




Figure 13

27. Select **End**.




Figure 14

28. Turn the ignition OFF, and then wait for 10 minutes.
29. Turn the ignition ON with the engine OFF.
30. Turn the hazard warning lights ON, and then wait for 15 minutes.
31. Turn the ignition OFF, and then wait for 10 minutes.
32. Turn the ignition ON with the engine OFF, and then wait for 15 minutes.

Intelligent Key Registration

33. Perform Intelligent Key registration for all customer Intelligent Keys.
 - Refer to the C-III plus operations manual for Intelligent Key registration instructions.

Verify Telematics Function

34. From the home page, select **Info**.



Figure 15

35. Select **System Information**.



Figure 16

36. Select **Software Update**.



Figure 17

37. Select **Start Software Update**.




Figure 18

- **Locating new software** should display as shown in Figure 19.



Figure 19

38. To confirm telematics functionality, ensure the screen in either Figure 20 or Figure 21 is displayed.



Figure 20

- If the screen matches Figure 20 or Figure 21, the procedure is complete.




Figure 21

- If the screen matches Figure 22, **(There is no current Wi-Fi connection)** repeat steps 28-32 on page 10 and verify telematics function starting at step 34.



Figure 22

39. Turn the ignition OFF.

CHECK-OFF SHEET

IMPORTANT:

- Follow all of the steps in this bulletin and use the check-off sheet provided below.
- **Staple the completed check-off sheet to the repair order.**

Perform the following if the TCU has been replaced:

- Complete the actions below in the order listed.
- Check off each action when it is completed.

| | CHECK BOX | ACTION |
|---|----------------------|-------------------------------------|
| 1 | | Configure TCU (1) |
| 2 | | Write VIN to TCU (2) |
| 3 | | Register Intelligent Key (3) |

(1) Refer to page 7, section **Configure TCU**.

(2) Refer to page 9, step 23, section **Write VIN to TCU**.

(3) Refer to page 10, step 33, section **Intelligent Key Registration**.

Manually Enter VIN Data (if needed)

NOTICE

If manually entering the VIN, double check that the VIN is correct before saving. Saving the incorrect VIN to the TCU can result in services not working and the TCU may need to be replaced, even after correcting the wrong VIN.

NOTE: The warranty claim will not be paid if the **NOTICE** above is not followed.

The following is only needed if automatic “SAVE VIN DATA” or “WRITE VIN (SAVED DATA)” did not complete correctly.

40. Select **WRITE VIN (MANUAL INPUT)**, and then select **Start**.




Figure 23

41. Enter the VIN:
 - a. Touch the **VIN (1ST TIME)** input field and type in the VIN.
 - b. Touch the **VIN (2ND TIME)** input field and type in the VIN again.

42. Select **Start**.




Figure 24

43. Select **End**.




Figure 25

Return to step 28 on page 10.

AMENDMENT HISTORY

| PUBLISHED DATE | REFERENCE | DESCRIPTION |
|-----------------------|------------------|--------------------------------------|
| April 6, 2020 | NTB20-029 | Original bulletin published |
| July 6, 2020 | NTB20-029a | Changes to page 1 and to steps 34-42 |