Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject: DISCHARGED BATTERY AFTER VEHICLE IS PARKED FOR MORE THAN 8 HOURS	Bulletin No.: 01-010/20
THAN 8 HOURS	Last Issued: 08/11/2020

APPLICABLE MODEL(S)/VINS

2019-2020 Mazda3 (Japan built) with VINS starting with JM1 2019-2020 Mazda3 (Mexico built) with VINS starting with 3MZ 2020 CX-30

DESCRIPTION

Some customers may experience a no start because the battery is discharged after the vehicle is parked for more than 8 hours. This may be caused by one or more of the following, resulting in excessive parasitic draw (dark current) on the battery.

- The vehicle control system may not have gone to sleep because a key fob was left in the vehicle after the ignition switch was turned off and the doors were closed. This is caused by improper BCM control logic which allows a higher parasitic draw (approx. 6A) to continue for approximately 6 minutes until the vehicle control system goes into sleep mode. If the doors are operated frequently for car washing or luggage loading/unloading etc., it prevents the vehicle control system from sleeping during that time.
- 2. The parking lights may have been left on because the warning sound for lights on is a short ding, and it may not be noticed.
- 3. [With Full-Auto A/C] The heater control unit may not have gone to sleep because the hazard warning switch was pressed after the ignition was turned off. This is caused by improper control logic of the heater control unit.

To correct these concerns:

- The control software of the body control module (BCM) has been modified to shorten the time until going into the sleep mode to approximately 2 minutes.
- The control software of the body control module (BCM) has been modified to change the lights on warning sound to a continuous one.
- The control software of the heater control unit has been modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

Page **1** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

REPAIR PROCEDURE

1. Verify customer concern.

2. [For 2019 Mazda3 5HB with advanced keyless entry] Check if MSP56 has been completed. Has MSP56 been completed?

- YES: Go to step 3.
- NO: Perform MSP56, then go to step 5.

3. Reprogram the BCM with the Mazda Modular Diagnostic System (M-MDS), using the Mazda Diagnostic And Repair Software (MDARS). Refer to "MDARS - ECU Reprogramming Procedure".

NOTE: If current calibration file name in the ECU FILENAME screen is the same as shown in Calibration Files Information or with later suffix, reprogramming is not necessary.

4. [For 2019 Mazda3 5HB with advanced keyless entry] If the BCM needs to be reprogrammed and the current LFU file name is NOT the same as shown in Calibration Files Information or with later suffix, reprogram the LFU. Refer to "MDARS - ECU Reprogramming Procedure".

5. Reprogram the IP-ESU (**CCU** on MDARS) using the Mazda Diagnostic And Repair Software (MDARS). Refer to "MDARS - ECU Reprogramming Procedure".

NOTE: If the Welcome Lamp function is accidently activated while using MDARS, it may also cause this concern. Check and correct as necessary. Refer to the SA-054/20 for details. 6. Verify repair.

MDARS ECU Reprogramming Procedure

NOTE: This procedure explains a generic reprogramming for all Electrical Control Units (ECU) such as PCM, BCM, ESU, etc. Be aware that some sentences and screen shots below mention a certain control unit such as "PCM" or "BCM" as an example.


ATTENTION: READ ALL CAUTIONS AND NOTES BEFORE AND AFTER REPROGRAMMING!

CAUTION:

- A poor connection between the vehicle and M-MDS and/or low voltage may result in abnormal termination and/or data corruption. A low battery voltage may cause a reprogramming failure resulting in unexpected ECU replacement.
- Make sure that the following connections are firmly connected, then DO NOT touch the VCM and DLC cable to prevent noise and a poor connection.
 - Between the vehicle-side connector and the DLC cable
 - Between the PC-side connector and the USB port of the PC
- When reprogramming with MDARS, power consumption and voltage fluctuation are greater than with IDS. Connect the GR8 battery charger and use Manual Mode set to 14.5 volts with no more than 10-15A charging current to the vehicle to minimize any voltage fluctuation.

Page **2** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



BEFORE REPROGRAMMING NOTE:

- Turn off all electrical loads (i.e. A/C blower, audio system, rear defogger and headlights).
- Perform a self-test and verify no DTCs are stored. If any DTCs are stored, repair the concern and delete the DTCs.
- Disconnect any aftermarket accessories (non-genuine Mazda accessories).
- Terminate all programs other than MDARS on the PC. Running other programs may interfere with the MDARS performance, resulting in the PC freezing or other problems.
- Perform reprogramming with a proper internet connection. When using a wireless network, make sure the connection is strong.
- Make sure to keep enough free space on the PC's hard disc. Insufficient free space (less than 1 GB) may result in the PC freezing during reprogramming.
- 1. Connect the M-MDS to the vehicle.
- 2. Launch the Mazda Diagnostic And Repair Software (MDARS).
- 3. Turn the ignition on, then click "Start".

Reade Diagnosic and Roser Software (VENRS	
mazpa	Change VCI
Vehicle Identification	Select another VCI. You do not need to do this unless you use a windess VCI.
Sart Mereman winder DMUKAWA (M), TEM	Continue Offline like fullow to continue within at a retwork contendim. You will be restricted on what you can do, stopporting so the data that has been propored.
Stan	Office Mode
	Start with no connected vehicle
	Use button to continue without connecting to a

Page **3** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Bulletin No.: 01-010/20	Last Issued: 08/11/2020

4. Select the "toolbox" tab.

ck Dec	Toobos						La
LEN .						_	ଏ
		104				-	
_							
	- 044	100.00	1000(151)0	DOOR, ESH, P		- 16	1945
esc.	- 195	1.00		106	1990	- 140	A MARINE
ite	100	-	- 141	100			

5. Select Work Support group.

Nozia Degroso and Nezie Salazie (MDRIS)		and the set
	0 налага 🖨 на плананастика – 😪 – П	🖬 🐮 tiv 🚍
A Question A Toolbox		
ए 🕱 6		* *
E Catalogger	Not Run	Bat
+ Confirmation test for system operation		
+ On-domand self-inst		
 Operational records 		
Sa Wesicke History	Not Run	Bat
A Battery low		0 x
A RECEIVED AND A RECEIVED		

Page **4** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

6. Select "Software update", then click "Run".

0 m	16204	🧿 наясаа (🖨 унслишникияларная) 🤰	3 421 🖬 LW 🗏
a Quic	k Chadk 🕺 K Toolbox		
Ŷ	ä #		¥ A
-	Software update		
1	Software opdate	Not Euro	Ban
+	Configuration		and the second s
+	ENGNE		
+	BRAKES		
+	THANSMISSION/THANSAALE		
+	RESTRAINTS		
+	SEATS		
+	SECURITY AND LOCKS		
+	LIGHTING SYSTEMS		
	WIPER/WASHER SYSTEM		

7. Select the ECU to be reprogrammed.

🖬 barna Clagnorty and Arpain Software (MCDRS)	
(C) macoa	🕒 valati i 🖨 varinamananan i 🔗 i 🛤 i 🌸 in 🚍
and Quick Check 🕺 Institution 📽 Software up 🗙	
ECU Reprogramming	^
Reprogrammable ECUs	
Scarch for an ECU	
rsc	,
WCM.	>
FSHL	>
ESHR	>
A Battery ice	01

Page **5** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

8. Confirm the current and new software versions, then click "Next". **NOTE:** When reprogramming the BCM, two softwares will be shown.

	194	-	100	
O m08112	🖌 🗛 viis aanaaaa	NORE20451/	2 10	1 🖬 IV 📰
				^
Current Version	Required Version	Size		
PA-188k2-A	P.K.(3-188K2-H	<u>1</u>	*	
			-	
				Next
	Current Version	Current Version Required Version	Current Version Required Version Size	


9. Wait for the download, then click "Next". **NOTE:** When reprogramming the BCM, downloading will occur twice.

MARTIN Diagnostic and Repair Sutwate (MDARS)		-		23	and Sale
() meszcea	O ##61222	🔒 чте лизанионакцонеза		1 💼 33+	=
🙀 (husk thesk 🔥 footbas 🖷 Software up- 🗙					
ECU Reprogramming					^
Downloading Vehicle Flash Files			Complete		
Downloading PCM PAJ3-188K2-H			Complete		
			1	Neid	


Page 6 of 10

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

10. Read the screen instructions, then click "Next".



11. Follow the instructions on the screen, then click "Next".



Page **7** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

12. Wait for the reprogramming to complete. **NOTE:**

- The progress bar will stay at 90% for 30 seconds. This is not a failure.
- When reprogramming the BCM, this process will occur twice.

	on Schone (1992)		100		S-STATISTICS.	
otingsoftware					=	
					1	
	3	StringPorts.				
	Men a De par de cara Branca	State Manual		1	-	Lesion.
	Updatingsoftwent					:
	1					
			Basang Propen	02		
			Mana Artubes	15%		
						Birter

AFTER REPROGRAMMING NOTE:

• Select "Vehicle History" under "Collect Diagnostic Information", then click "Run".

-	a Degrattic and Repair Software (MDARS)		Restaura
9"	NSCO0	😧 editati 🔗 vin Autorevinatione 💍 🛍	🗱 🔟 Dy 🗄
a Quint	A Dock A Toolbox		
Y	X +		v A
÷	TRANSMISSION/TRANSAGLE		
+	RESTRAINTS		1
+	SEATS		
+	SECURITY AND LOCKS		
+	LIGHTING SYSTEMS		
+	WIPER/WASHER SYSTEM		
+	POWER SYSTEMS		
+	FACTIVISENSE		
+	Mazda Connect		
+	Collect Diagnostic Information		
0	Wehicle History	Not Bun	liet.

Page 8 of 10

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Confirm the reprogramming on the screen and save the screen copy as a record.

Maple Deposite and Repair Softwa	THE (MEDARES)				and the second second	ACTIVITY OF
💬 meszcea		0	NORE 222 🙈 VIII	MORANGEORES	8 100	🛍 IV 🗮
Quick Check 🔥 Toolbox 🔒	Vehicle Hist— 🗙					
ug 26, 2019 1:07 PM						0
	<	Aug 26, 2019 1:07-40	11M >			
Quick Check > Rehesh DTCs	8/26/191.34198	Status SUCCESS			Durati	on: 178 seconds
Quick Check + Clear DTCs	R/26/19.1.36 PM	DASH_ESU	010	NE		
Quick Check > Refresh DTCs	8/26/19 1.36 PM	\$773.54	8067-66531-8		GF 66511-J	
Quick Check > Refresh DICs	8/26/19 1:37 PM					
Software update	8/26/29 1.39 PM					
Software update	NO6/19 140 PM					
Quick Check > Refresh DECs	8/26/19 1-43 FM					
Quick Check - Clear DTCs	R/26/19 1-44 PM					
Quick Check > Refresh DTCs	8/26/29 LA4 PM					
Outck Check + Rehesh DTCs	8/26/191.45 PM					

CALIBRATION INFORMATION

Spec	Model	Body	File Name	
			BCM_MAIN	BCM_SUB (*)
Japan Built	Mazda3	5HB	BEMD-66S02-S	BCKP-66S03-
		4SD	BCKA-66S02-V	BCKP-66S03-
Mexico Built	Mazda3	4SD	BDTS-66S02-S	BCKP-66S03-
	CX-30	5HB	DGH9-66S02-H	BCKP-66S03-

NOTE(*): For further updated BCM_MAIN file name, BCM_SUB file name may vary.

Spec	Model	Body	File Name	
			LF control unit (LFU)	
All	Mazda3	5HB	BCWK-66S06-E	

Spec	Madal	File Name	
	Model	Heater control unit (CCU)	
All	Mazda3, CX-30	BDGG-66S12-F	

Page **9** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

With BCM Reprogramming:

Warranty Type	A
Symptom Code	64
Damage Code	9W
Part Number Main Cause	5555-67-560
Quantity	0
Operation Number / Labor Hours:	Reprogramming BCM only: XXS4MAFX / 0.3 Hrs. Reprogramming both units: XXS4MBFX / 0.3 Hrs.

Without BCM Reprogramming:

Warranty Type	А
Symptom Code	64
Damage Code	9W
Part Number Main Cause	5555-61-190
Quantity	0
Operation Number / Labor Hours:	XXS2MXFX / 0.3 Hrs.

Page **10** of **10**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.