

**Noise Symptom - Rattling Noises From the Fuel Tank Area: Replacing Fuel Tank With New Type of Fuel Tank (SY 104/20)**

Vehicle Type: **Cayenne (9YA)/Cayenne Coupé (9YB)**

Model Year: **As of 2018 up to 2020**

Country/Market: USA (C02)  
Canada (C36)

Equipment: 6-cylinder turbo engine, 3.0 l (l-no. DU6)

Subject: **Fuel tank**

Symptom: Rattling noises can be heard from the fuel tank area at idle speed.

Cause: During tank vent valve flushing, the pulsation damper does not have a sufficient damping effect and this can result in rattling noises. The problem occurs when the fuel tank is about 3/4 full.

Remedial Action: In the event of a customer complaint **and if the problem is clearly present**, replace the fuel tank with a new type of fuel tank, see ⇒ *Workshop Manual '201019 Removing and installing fuel tank'*.



**Information**

The fuel tank with modified seal (Part No. 9Y0201060) must only be installed in the event of a complaint involving the noise described here. Use the standard fuel tank for all other repairs.

**Parts required**

Parts Info:	Part No.	Designation - Use	Qty.
	9Y0201060	⇒ Fuel tank	1 ea.
	N 91205201	⇒ Cheese head bolt with multiple-tooth head - Rear seat	2 ea.
	PAF912664	⇒ Hexagon flange bolt - Rear seat	2 ea.
	N 91228001	⇒ Hexagon flange bolt - Rear axle	4 ea.
	N 91236401	⇒ Hexagon-head bolt - Rear spring damper	2 ea.

N 10106403	⇒ Hexagon collar nut – Rear spring damper	2 ea.
PAF912225	⇒ Hexagon-head bolt – Rear spring damper	4 ea.
9A700758500	⇒ Cheese head bolt (I-no. 1KV, 1KR, 1KX) – Rear brake calliper	4 ea.
	<b>or</b>	
N 91183701	⇒ Cheese head bolt (I-no. 1KS, 2EN, 2EL, 2EQ, 2ES) – Rear brake calliper	4 ea.
	<b>or</b>	
N 91252201	⇒ Cheese head bolt (I-no. 1KK, 1KI) – Rear brake calliper	4 ea.
N 10772201	⇒ Hose clamp (I-no. T9I, TV8, OK0) – Cardan shaft	1 ea.
	<b>or</b>	
PAF10848901	⇒ Hose clamp (I-no. T1M, OK0, OK3) – Cardan shaft	1 ea.
95534919121	⇒ Plate – Cardan shaft	3 ea.
PAF107599	⇒ Cheese head bolt with multiple-tooth head – Cardan shaft	6 ea.
PAB25311520	⇒ Seal (I-no. T9I) – Catalytic converter	1 ea.
N 91130802	⇒ Hexagon collar nut (I-no. T9I) – Catalytic converter	3 ea.

## Invoicing

Invoicing: For documentation and warranty invoicing, enter the labor operations, PQIS coding and part numbers specified below in the warranty claim:

APOS	Labor operation	I No.
20105501	Replacing fuel tank	

PQIS coding:

Location (FES5)	20230	Tank vent valve
Damage type (SA4)	2024	rattling

Parts Info:	Part No.	Designation – Use	Qty.
	9Y0201060	Fuel tank	1 ea.
	N 91205201	Cheese head bolt with multiple-tooth head – Rear seat	2 ea.
	PAF912664	Hexagon flange bolt – Rear seat	2 ea.
	N 91228001	Hexagon flange bolt – Rear axle	4 ea.
	N 91236401	Hexagon-head bolt – Rear spring damper	2 ea.
	N 10106403	Hexagon collar nut – Rear spring damper	2 ea.
	PAF912225	Hexagon-head bolt – Rear spring damper	4 ea.
	9A700758500	Cheese head bolt (I-no. 1KV, 1KR, 1KX) – Rear brake calliper	4 ea.
		<b>or</b>	
	N 91183701	Cheese head bolt (I-no. 1KS, 2EN, 2EL, 2EQ, 2ES) – Rear brake calliper	4 ea.
		<b>or</b>	
	N 91252201	Cheese head bolt (I-no. 1KK, 1KI) – Rear brake calliper	4 ea.
	N 10772201	Hose clamp (I-no. T9I, TV8, OK0) – Cardan shaft	1 ea.
		<b>or</b>	
	PAF10848901	Hose clamp (I-no. T1M, OK0, OK3) – Cardan shaft	1 ea.
	95534919121	Plate – Cardan shaft	3 ea.
	PAF107599	Cheese head bolt with multiple-tooth head – Cardan shaft	6 ea.
	PAB25311520	Seal (I-no. T9I) – Catalytic converter	1 ea.
	N 91130802	Hexagon collar nut (I-no. T9I) – Catalytic converter	3 ea.

**or**

PAB253115	Seal (I-no. T9I with petrol particulate filter) – Catalytic converter	2 ea.
N 91130802	Hexagon collar nut (I-no. T9I with petrol particulate filter) – Catalytic converter	6 ea.

References: ⇒ *Workshop Manual '201019 Removing and installing fuel tank'*

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.