

**95B Instrument Cluster Pointers Flutter at Startup**

**Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan II	2019 - 2020	95B	N/A	N/A

**Revision History**

Revision	Release Date	Changes
0	August 10, 2020	Original document

**Condition**

On startup, after the typical instrument cluster self-test, the tachometer and speedometer pointers flutter or bounce and the led indicator lamps all light up (as shown in figure 1). After a few seconds, behavior returns to normal for the rest of the drive cycle. The issue occurs intermittently.



Figure 1

### Service Information

Porsche will release information and a permanent solution to this issue in the near future. In the meantime, **do not replace any parts**. Part replacement is not an effective repair.

### Warranty

Please be sure to document your findings in PQIS thoroughly.

Use the following PQIS coding:

Cause location: 90250

Instrument cluster

Cause symptom: 4034

Switching off/on automatically

### Search Items

IC, Macan, bounce, needles

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

---