

19 Red coolant light or engine speed light, DTC P059900, P059700, and/or P218100 is stored in the ECM

19 20 08 2042328/5 September 4, 2020. Supersedes Technical Service Bulletin Group 19 number 17-92 dated October 25, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2011 - 2012	All	4.2 FSI
S5	2008 - 2012	All	4.2 FSI
RS5	2013 - 2015	All	4.2 FSI

Condition

REVISION HISTORY				
Revision	Date	Purpose		
5	-	Revised title Revised Require Parts and Tools (Updated part numbers)		
4	10/25/2017	Revised title (Updated formatting) Revised Require Parts and Tools (Updated part number)		
3	05/22/2017	Revised Warranty (Updated Service Number, Labor Operations, and Claim Type)		

Customer states:

One or more of the following conditions is present:

- The red coolant light is illuminated (Figure 1), indicating that the coolant temperature is too high or that the coolant level is too low.
- The engine speed governing light is illuminated (Figure 1) with the message "Engine speed maximum XXXX rpm". To prevent the engine from overheating, the engine speed is automatically limited to the displayed maximum.





Figure 1. Engine speed governing light (left) and red coolant light (right).

Workshop Findings:

One of the following DTCs is stored in the engine control module (ECM), J623 (address word 0001):

• DTC P059700 (Thermostat for map-controlled engine cooling F265, circuit open).



- DTC P059900 (Thermostat for map-controlled engine cooling F265, short circuit to positive).
- DTC P218100 (Fault in cooling system).

Technical Background

Tolerances of opening spring in thermostat cause the condition.

Production Solution

Modified coolant thermostat housing.

Service

If one of the DTCs listed in the *Condition* is stored, replace the coolant thermostat housing for map-controlled engine cooling (Figure 2).

It is not necessary to replace the complete coolant pump.



Figure 2. Coolant thermostat housing for mapcontrolled engine cooling.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	1958
Damage Code:	0010



Labor Operations:	Thermostat housing remove + reinstall	1958 1919 (For S5) Or 1958 1921 (For RS5) Or 1958 1919 (For A8)	See SRT with associated operations
Diagnostic Time:	GFF – check and clear faults codes	0150 0000	Time stated on the diagnostic protocol (Max 10 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2042328/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.			
Part Number	Part Description	Quantity	
079121115BG	Map controlled engine cooling thermostat F265	01	
GA137741GDSP	Coolant additive	01	
N/A	Distilled water	Shop supply	
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA	

Tool Number	Tool Description
VAS 6096	Cooling system charge unit
VAS 6208	Drip tray
T10007A	Refractometer



Additional Information

All parts and service references provided in this TSB (2042328) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites w