



Technical Service Bulletin

91 Parking assist alert showing an active false positive, various DTCs may be stored

91 20 14 2060675/1 September 17, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2018 - 2021	All	Not Applicable

Condition

Customer states:

- The parking assist intermittently alerts them to an obstruction in spite of there being no object in front of the vehicle.
- They may also state that one or more of the park assist sensors in the front grille appear to be 'pushed in' (Figure 1).



Figure 1. Park assistance sensor not properly fixed in position.



Technical Service Bulletin

Technical Background

The electronic central electrical (BCM) control module, J519 (address word 0009) may have one or more DTCs stored that indicate a technical issue with either the front or rear park assistance system. The park assistance sensor holder is found to be de-bonded from the component to which it was attached (front bumper, rear bumper, front grille, etc.).

Production Solution

Not applicable.

Service

Scenario 1:

- In some cases a replacement sensor holder is available as well as a technical description for its reattachment to the component. In these cases repairs can proceed as directed in the repair manual.

Scenario 2:

- In cases where the sensor holder is not available separately, then replace the entire component.
- In these cases be sure to retain the park assistance sensor holder(s) that have come loose.

WPRC Instructions:

- The park assistance sensor holder(s) will be required to accompany the component from which it has de-bonded when the component is requested by the WPRC for part submission (Figures 2 and 3).



Figure 2. Park assistance sensor holder de-bonded from a front grille.



Technical Service Bulletin

- Attach the sensor holder(s) to the component securely marking the position from which they were mounted.



Note:

Components received in the WPRC that do not include the sensor holders will be returned and the claim debited.



Figure 3. Park assistance sensor de-bonded from a rear bumper cover.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2060675) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.