



92-20-01TT - Windshield Wiper Operation with Fault B12D600, May Occur in Heavy Rain

Release date: 09/29/2020

## Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.  
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

### Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta	2018 - 2020	All	All	All	All

### Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2060812/2	9/29/20	92-20-01TT	Administrative.
2060812/1	9/18/20	92-20-01TT	Original publication.

## Technical Background

Wipers may have an operational issue, which may occur in heavy rain. Faults may include but are not limited to B12D600, U014100, U112100, U111000.

## Service

Inspect the wiring for wiper relay 1 -**J368**- and wiper relay 2 -**J369**- at the under the hood relay panel. Test the terminals by performing a pin drag test, including the connecting circuit between these relays (Figure1). If a terminal issue is found for this connecting circuit, install a new connecting circuit, (Figure 2) with new terminals. See Repair Group 97 in Elsa.



Figure 1




Figure 2

### Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.