TECHNICAL TOPICS BODY/CHASSIS





HVAC Lack of Airflow	20MY Discovery
 <u>Customer Voice</u>: A customer may report a lack of airflow through the face vents. <u>Technical Description</u>: An interrogation of DTCs identifies B13EF-92 stored in the HVAC module. A limited number of vehicles may have been built without required foam padding from one side of the air mode door. 	
 <u>Status</u>: Engineering have developed a fix for this concern by adding a special foam pad to the HVAC case. A TSB will be published for this concern and the foam pad will be made available through normal parts ordering process. Should a customer express a concern before a formal TSB is published, please submit a TA case so repair instructions can be provided. 	

PRINTED COPIES ARE UNCONTROLLED