

# **Technical Journal**

#### TITLE:

# Headlight DTC's after software upgrade

REF NO: TJ 35560.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
3 US 7	PARTNER: 510 Volvo Car USA	ISSUE DATE: 2020-09-11	STATUS DATE: 2020-09-18	
FUNC GROUP: 3524	FUNC DESC: Leveling control, headlamp	Pago	1 of 2	
3324	Leveling Control, Headlamp	Page 1 of 2		

"Right first time in Time"

## **Vehicle Type**

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2020-2021	25	0050159-9999999	201946-202022
224							2020-2021	70	0030001-9999999	201946-202022
225							2020-2021	21	0347020-9999999	201920-202022
225							2020-2021	22	0347035-9999999	201920-202022
227							2020-2021	21	0030000-9999999	201920-202022
234							2020-2021	25	0078027-9999999	201920-202022
234							2020-2021	35	0078019-9999999	201920-202022
235							2020-2021	21	0124000-9999999	201920-202022
236							2020-2021	21	0101000-9999999	201920-202022
238							2020-2021	35	0136000-9999999	201920-202022
246							2020-2021	21	0410083-9999999	201920-202022
246							2020-2021	36	0410065-9999999	201920-202022
256							2020-2021	21	0530000-9999999	201917-202022

## **CSC** Customer Symptom Codes

Code	Description	
YY	Auto position/Does not work	
DC	Headlights/Headlight aim is off	

# **Technical Journal 35560.3.0**



#### **VST** Operation Number

<b>VST Operation Number</b>	Description
36050-2	Calibration/Identifying with VIDA

#### **DTC** Diagnostic Trouble Codes

<b>Control Module</b>	Code	Fault Type
CEM	B14C281	Intermittent
VCU1	B104154	Intermittent

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

#### **DESCRIPTION:**

If DTC's are set after Software upgrade for missing calibration on headlights, please see advice under service.

#### **SERVICE:**

If the DTC's are confirmed, perform a calibration of the position sensors, follow instruction described in VIDA:

\*Planning & Daignostics => Diagnostics => Components => Vehicle Computational Unit 1 (VCU1) => Diagnostic Sequences => Calibration of position sensor

#### Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 36050-2

#### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3524.

Page 2 of 2 2020-09-18

<sup>\*</sup>Note! Do not perform headlight adjustments before software upgrade.