



NUMBER: 18-075-20

GROUP: 18 - Vehicle Performance

DATE: September 1, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 18-055-18 REV. A, dated December 07, 2018, which should be removed from your files. All revisions are highlighted with **asterisks**** and include additional symptom/conditions, Diagnostic Trouble Codes (DTCs) for the ED6 engine and LOP.**

SUBJECT:

Flash: Powertrain Control Module (PCM) Updates

OVERVIEW:

This bulletin involves reprogramming the PCM with the latest available software.

MODELS:

2018 (M6) Jeep Compass

NOTE: This bulletin applies to vehicles within the following markets/countries: APAC and EMEA.

NOTE: This bulletin applies to vehicles equipped with a 2.4L I4 Engine (Sales Codes EDD and ED6).

SYMPTOM/CONDITION:

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that the following DTCs have been set:

- C050D - Wheel Speed Signal Left Rear Rationality.
- C0501 - Wheel Speed Signal Left Front Rationality.
- C0507 - Wheel Speed Signal Right Front Rationality.
- C0513 - Wheel Speed Signal Right Rear Rationality.
- P0340 - Camshaft Position Sensor Circuit - Bank 1 Sensor 1.
- P0335 - Crankshaft Position Sensor Circuit.
- P0339 - Crankshaft Position Sensor Intermittent.

****In addition, customers may experience the following concern:**

- When using the adaptive cruise control and coming to a complete stop, the MIL light illuminates **(ED6 engine only)**.

In addition, the following software enhancements to the following DTCs:

- B25BC - Left Front Door Ajar Switch Stuck Closed **(ED6 engine only)**.
- P0573 - Brake Switch 1 Stuck Off **(ED6 engine only).********

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed or if the technician finds the DTC, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: The Transmission Control Module (TCM) must be updated to the latest available software at the conclusion of this repair procedure. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
3. Verify the TCM is programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the TCM software.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-06-CV	Module, Powertrain Control (PCM) - Reprogram (0 - Introduction)	1 - Engine Repair and Performance	0.3 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 6 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must use failure code CC with this Service Bulletin.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.

CC	Customer Concern
----	------------------

