

# Service Update

## N202305180 Front Camera Module Reset and Loss of Communication



**Release Date:** September 2020

**Revision:** 00

**Attention:** This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

Make	Model	Model Year		RPO	Description
		From	To		
Cadillac	CT4	2020	2020	UEU	Forward Collision Alert
Cadillac	CT5				

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition</b>	Certain 2020 model year Cadillac CT4 and CT5 vehicles may have a condition where the front windshield camera module may reset and lose communication with other modules. DTCs P25A2, U0265, U0566 and U1962 are set. The malfunction indicator light (MIL) may illuminate.
<b>Correction</b>	Reprogram the front view camera.

### Parts

No parts are required for this repair.

### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9105139	Verified Module Software or Calibration Level: Module Is Programmed with Same Level Software or Calibration	0.2	ZFAT	N/A
9105140	B174W Front View Camera - Windshield: Programming and Setup	0.5		

### Service Procedure

**Note:** Carefully read and follow the instructions below.

- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to [www.gmdesolutions.com](http://www.gmdesolutions.com) for further information. If not available, connect a fully charged 12V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Ensure the ignition is turned OFF, load on the vehicle's battery such as; interior lights, exterior lights (including daytime running lights), HVAC, etc. may affect the download process.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.

# Service Update

## N202305180 Front Camera Module Reset and Loss of Communication



Techline Connect  
Version: 1.6.0 Validation

2021 • Chevrolet • Camaro

MDI 2 SN#: 00737023  
Click to disconnect

DASHBOARD GDS2 SI SPS2 Support RPO Search Service Manuals

SPS2

### Electronic Brake Control Module - Programming

Controller	ID	Current #	Description
K17	1	84820771	
K17	2	84820790	
K17	3	84820797	Electronic Brake Diagnostic Calibration
K17	4	84820801	Function Enable Calibration
K17	5	84820808	Driver mode brake calibration
K17	6	84820819	Tire Pressure Calibration
K17	7	84820825	Caliper Assist Calibration

M4521: You are attempting to reprogram with the same calibration.  
Select OK to continue, Cancel to Stop!

Print Save to PDF ECU Data Back Start Programming Cancel

5644477

Service Programming System

### Summary

#### Brake System Control Module

Controller	Id	Current #	Selected #	Description
K160	1	84758789	84758789	New software for start of production
	2	84790857	84790857	New calibration for start of production
	4	84557555	84557555	Function Enable Calibration
	5	84681582	84681582	Updated Calibration to improve diagnostics for DTCs C05B0 and C058E.
	7	84690692	84690692	Caliper Assist Calibration
	8	84662691	84662691	
	9	84678464	84678464	

M4521: You are attempting to reprogram with the same calibration.  
Select OK to continue, Cancel to Stop!

Vehicle Data

Attribute	Value

VIN: 3GTU9DET7LG100114

Print < Back Next > Cancel

5431207

**Important:** Techline Connect and TIS2WEB screens shown above.

**Important:** If the Same Calibration/Software Warning is noted on the TLC or SPS Summary screen, select OK and follow screen instructions. After a successful programming event, the WCC is located in the Service Programming System dialogue box of the SPS Summary screen. No further action is required. Refer to the Warranty section of the bulletin.


# Service Update

## N202305180 Front Camera Module Reset and Loss of Communication




**Important:** When programming a module in GM's new Vehicle Intelligence Platform, or VIP, the power mode (ignition) needs to be off or errors may occur. This involves the 2020 Chevrolet Corvette, Cadillac CT5 and CT4, as well as the upcoming full-size Chevrolet, GMC, Cadillac SUVs and Buick Envision. Serial Data Message Authentication also needs to have the ignition off.

1. Reprogram the front view camera. Refer to *B174W Front View Camera - Windshield: Programming and Setup* in SI. Modify as required (e.g., select x module from the controller screen. Then provide step-by-step instructions or refer to SI procedure.



5644478



5431209

## Service Update

# N202305180 Front Camera Module Reset and Loss of Communication



**Important:** To avoid warranty transaction rejections, you **MUST** record the warranty claim code provided on the Warranty Claim Code (WCC) screen shown above on the job card. Refer to callout 1 above for the location of the WCC on the screen.

- Record SPS Warranty Claim Code on job card for warranty transaction submission.

### Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.



GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5505  
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 17, 2020

Subject: N202305180 - Service Update  
Front Camera Module Reset and Loss of Communication

Models: 2020 Cadillac CT4 equipped with Forward Collision Alert (RPO UEU)  
2020 Cadillac CT5 equipped with Forward Collision Alert (RPO UEU)

To: All General Motors Dealers

General Motors is releasing Service Update N202305180 today. The total number of U.S. vehicles involved is approximately 10,676. Please see the attached bulletin for details.

**Global Warranty Management (GWM)**

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated September 18, 2020 or sooner. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS