

Subject: AUDIO, NAVIGATION AND PHONE CONCERNS WITH MAZDA CONNECT INFOTAINMENT SYSTEM (7TH GENERATION MODELS)	Bulletin No.: 16-001/20
	Last Issued: 10/13/2020

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previous TSBs	Issued Dates:
16-001/20	04/08/20 and 3/04/20

APPLICABLE MODEL(S)/VINS

2019-2021 Mazda3
2020-2021 CX-30

DESCRIPTION

Some vehicles may experience the symptoms mentioned below, which can be fixed with the latest software update (Version 7000C0A-NA01_11012 or later).

NOTE: Device compatibility can be found at connect.mazda.com - Support - Compatibility.

MAZDA CONNECT Software Version 11002 NOTE:

Mazda3 owners may notice an icon in their infotainment's display that indicates Mazda Connected Services. This new feature is a global technology and designed with the latest version of Mazda Connect™. At this time, the service is not active for Mazda3 vehicles in the U.S. Any updates to the service will be announced at the appropriate time.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

(Ver. 7000C0A-NA01_11012)

- A “Loading” pop up message continues and it cannot move to Parking Information screen if there is no parking information around the destination.

(Ver. 7000C0A-NA01_11008)

- DTC U3000:49 (CMU internal malfunction) is detected when music play is disturbed by another mobile device application.
- Voice command for artist name or album name is not accepted with error message “Voice Recognition Unavailable. Voice Recognition commands for music are unavailable. There is no available metadata on this device.”
- The system may reboot when the Wi-Fi services start.
- The system may freeze at the phone call screen if Bluetooth connection has been interrupted when using voice command “Call Time Signal”.

(Ver. 7000C0A-NA01_11006)

- [Connected Service is in use] Authorization using One Time Password may fail.
- [While the cursor is shown in the navigation screen after a commander operation] When Talk/Pickup button is pressed and "Go Home" is spoken, the navigation screen is shown but the commander operation is not accepted and the cursor is not shown.
- The 21th title is shown at the top when using Bluetooth audio and scrolling title list to the bottom.
- The system reboots when making a call with voice command. It occurs when making a call to the contact who contains two or more single quotation marks in the phone book downloaded from a mobile phone.
- The system reboots while the disclaimer notice screen is shown.
- [Connected Service is in use] After sending destinations from Send To Car function on MyMazda app several times, the navigation may reboot because of a poor wireless connection.
- The second track on certain CDs will not play. After experiencing this, even with another CD, the track selection and control fail until the ignition is turned off.
- Voice recognition command to select a track may clear the random mode icon while it continues the random mode when using a USB audio device in random play mode,.
- The system reboots when recovering from the sleep mode.
- The parking assist screen continues to display.
- The DTC may not be detected for communication error between CMU and the Telematics communication unit.
- After adding a favorite destination for a road or street without a valid name, it appears as “Unnamed road.” It should be the latitude and the longitude.
- The system may freeze when cranking right after turning the ignition on if the ignition has been turned off showing the navigation screen while playing a USB audio device.
- After SMS messages are received while one of the certain system dialog (such as a disclaimer screen for AndroidAuto or CarPlay) is displayed, it may not be able to move to the communication menu.
- The system may reboot when trying Bluetooth connection using certain mobile device (Doro 7060).
- The system may reboot when using the map function on CarPlay.
- The system may not recognize AndroidAuto after turning the ignition off when using the navigation screen and playing AndroidAuto Music.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by “do-it-yourselfers.” Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- Insufficient storm details may appear when using SiriusXM weather radio.
- The navigation may not show a green dot on the map where there is right/left turn guidance.
- When returning from the detail screen, the focus moves to Add Destination button instead of high way mode area while using navigation and displaying high way mode area. The concern occurs after moving the focus to the high way mode area using split screen button, then to the detail of high way exit.
- The background screen blinks with pop up message "Route Notification" after setting the destination in the country where the navigation map is not applicable.
- Route guidance ends just before the arrival announcement.
- The destination flag disappears just before arriving there.
- [Connected Service is in use] Route guidance may start without waiting for the OK button for SendToCar setting completion.
- The navigation may reboot when receiving big data for SiriusXM weather radar.
- Nothing appear in Turn-by-Turn display area when going off the guided route,
- SiriusXM Fuel price is not shown in colors.
- SiriusXM Weather Radar does not keep display setting for Storm after turning ACC off.

(From Version 7000C0A-NA01_10048 or later)

- The screen turns black if the ignition switch is turned OFF then ON within a few seconds while the opening screen appears.
- The Google Map navigation stops after already being in use when the Android Auto application is launched,
- No warning popup message appears when another destination is added which has to cross a border with "Allow Border Crossing" unchecked.
- A warning popup message appears repeatedly when another destination is added which has to use a car shuttle train with "Allow Car Shuttle Trains" unchecked
- If the "Allow Car Shuttle Trains" setting is changed after the route is set up, the "Allow Ferries" setting changes instead.
- A wrong warning popup message appears as "The destination cannot be reached without using a ferry" when the route is set up which has to use a car shuttle train with "Allow Car Shuttle Trains" unchecked.
- Pressing the Back button leads to the Information screen instead of the previous page while using the In-Vehicle Owner's Manual.
- The Communication Setting screen and the HOME screen may appear to overlap.

(From Version 7000C0A-NA01_10042 or later)

- If the system freezes, it may be followed by a reboot a couple of minutes later.
- The banner message about Bluetooth Audio may not appear when turning it ON.
- An improper message appears when GPS reception is not available.
- The rear view does not appear when the transmission is shifted to reverse right after turning the ignition on.
- The current location does not move after rebooting the navigation.
- The side panel turns black if reroute search occurs while using navigation with media display in the side panel.
- No warning popup message appears when another destination is added which has to use a toll road with "Allow Toll Roads" unchecked.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- No warning popup message appears when another destination is added which has to use a Carpool/HOV Lane with "Allow Carpool/HOV Lanes" unchecked and "Allow Carpool/HOV Lanes" is checked by itself.
- In the Energy Flow Monitor, the graphic blinks during idling.
- The guidance message may not sound when the ignition is turned OFF right after the route setting.
- An abnormal Route Settings menu appears for a moment during reroute search in route setting menu instead of the notification.
- The alphabetical search is not accessible after sorting the history list in the "More Recent Destinations" when driving.
- Road names may not appear in Turn-by-Turn and Route Monitor.
- Street names may not completely appear.
- The complicated Turn-by-Turn icon may appear.
- The same destination may be registered as multiple listings in Favorite Destination if the destination has multiple addresses (ex. large facility like a golf course).
- The keyboard and footer bar may appear to overlap.
- The status bar may appear for a moment when pressing the Back key to move to Travel Information in the Country Information screen.
- Additional registering of a favorite destination may not be accepted after registering a favorite destination right after the MAZDA CONNECT boots up.
- After registering a country (or state/province) other than the current location for a favorite destination, that country may appear in the country field in the Town Selection screen.
- It may take a long time until the free word search (OneBox search) screen appears after selecting the Navigation Menu Search.
- The screen flickers after switching from 3D to 2D on the View Mode screen.
- The Media panel may appear improperly.
- The traffic information for a non-relevant location may appear when a grouped traffic icon is selected on the map when using SiriusXM Traffic Plus.

From Version 7000C0A-NA01_10018 and later)

- The navigation system unexpectedly makes an announcement when the driver unlocks and opens the door, even without touching the START/STOP button.

(From Version 7000C0A-NA01_10017 and later)

- The compass screen may be displayed instead of the map screen after the ignition is turned ON,
- The In-Vehicle Warning Messages screen displays warning comment for "MRCC being not operable" and uses "30 km/h" instead of "20 mph" even when "mile" is selected in the distance setting.
- The sytem may reboot when connecting to a Bluetooth device.
- Destinations may be cleared when the ignition is turned OFF and ON while route guidance is being given.
- [Canada, Mexico] The navigation system unexpectedly announces when the vehicle passes the border to another country.
- The system may reboot when too much information is received using the SiriusXM SportsFlash service.
- [Alaska (U.S.)) Point Of Interest searching may not work properly.
- The system reboots when using Apple CarPlay.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

(From Version 7000C0A-NA01_10015 and later)

- The check box for Bluetooth connection may not be accessible after the ignition is turned OFF to ON in a few seconds.
- The device names for USB1 and USB2 may be displayed in the reverse order after the ignition is turned ON.

(From Version 7000C0A-NA01_10014 and later)

- There may be an excess error in the current location on the navigation screen where GPS reception is poor.
- The rear view monitor may turn black or need longer time to display during hot weather.
- The Apple CarPlay icon is left on the screen when the USB cable for an iPhone is disconnected,
- The rear view monitor turns to black when the transmission is shifted into reverse right after the engine is started,
- A guidance message is accompanied by a pop noise when using Apple CarPlay.
- The system reboots when the ignition is turned ON when an iPhone and a USB memory stick are connected
- The system may reboot while the disclaimer notice screen is shown.
- The USB connections may be disrupted when the ignition is turned ON with two USB devices connected and the navigation SD card in the slot, .

(From Version 7000C0A-NA01_10012 and later)

- The right most gauge for the last one minute shows the maximum level when the ignition is turned OFF and ON while displaying the Average Fuel Efficiency History.
- The rear view does not appear soon enough when the transmission is shifted into reverse right after the map is displayed the first time,.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.

2. Update MAZDA CONNECT with software version 7000C0A-NA01_11012 or later using the 7TH GEN MAZDA CONNECT Update Instructions on MGSS.

CAUTION: More than one software version can be placed on a memory stick, but Mazda recommends placing only one version on a memory stick to avoid updating the system with the wrong version.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3. [For 2019 Mazda3 only] (Additional repair procedure): When the CMU is updated from older version than 7000C0A-NA01_10040, the TCU and the BCM need to be reprogrammed together to have the vehicle be ready for activation of the connected service. If they are not reprogrammed, communication error between CMU occurs.

a. Reprogram the TCU and the BCM with the Mazda Modular Diagnostic System (M-MDS), using Mazda Diagnostic And Repair Software (MDARS) and claim the labor hours according to the warranty information shown below.

- After CMU update, an additional button appears at the right bottom corner of the screen. This means that the communication unit is unsubscribed or a Connected Service contract has been ended.
- After CMU update, “Wi-Fi Settings” is added to the Connectivity Settings but it is grayed out and not active.
- If current calibration file name in the ECU FILENAME screen is same as shown below or with later suffix, reprogramming is not necessary.
- [5HB] If the vehicle is applicable to the Mazda Service Program MSP56, performing the MSP56 repair procedure updates BCM (and LFU) to the modified version.

ECU name	Body	File name
TCU	Japan built	BDGF-67CK2-B
	Mexico built	BDTS-67CK2-A
BCM	Japan built 4-door SD	BCKA-66S02-R
	Mexico built 4-door SD	BDTS-66S02-M
	Japan built 5-door HB	BEMD-66S02-M

b. Perform “Activation Remote Control by Smart Phone” using M-MDS. Without performing this, DTC U2050:55-TCU and/or U2050:55-BCM will be stored.

On MDARS screen, follow these steps: “Tool box” tab “Work support” icon “Mazda Connect” “Activation Remote Control by Smart Phone”

4. Verify repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by “do-it-yourselfers.” Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	61
Damage Code	9W
Part Number Main Cause	5555-RP-CMU
Quantity	0
Operation Number / Labor Hours:	XXS1HAFX / 0.4 Hrs.

NOTE: [For 2019 Mazda3] If the TCU and/or the BCM has been updated together, claim additional hours using the labor operation number with "XFT" instead of the last three letters "AFX".

Additional reprogramming	Additional hours
TCU	0.1 Hrs.
BCM	0.1 Hrs.
TCU and BCM	0.2 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Example:

Additional reprogramming	Additional hours
Reprogramming CMU	XXS1HAFX / 0.2 Hrs.
With reprogramming TCU	XXS1HAFT / 0.3 Hrs.
With reprogramming BCM	XXS1HAFT / 0.3 Hrs.
With reprogramming TCU and BCM	XXS1HAFT / 0.4 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.