

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: DTC U2050:55 STORED AFTER REPLACING OR REPROGRAMMING TCU	Bulletin No.: 09-013/20
	Last Issued: 10/06/2020

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previously issued TSBs:	Date issued:
09-013/20	05/08/20
09-013/20	04/10/20

APPLICABLE MODEL(S)/VINS

2019 Mazda3 vehicles (Japan built) with VINS lower than JM1BP*****147656 (produced before June 29, 2019)

2019 Mazda3 vehicles (Mexico built) with VINS lower than 3MZBP*****115095 (produced before June 29, 2019)

DESCRIPTION

When the Telematics Communication Unit (TCU) has been replaced or reprogrammed and the software is updated to ones shown below, DTC U2050:55-TCU (Activation of remote control not implemented) may be stored in memory with the message "In-Vehicle Network Malfunction" displayed in the multi-information display.

- Japan built vehicles: BDGF-67CK2-B or later suffix.
- Mexico built vehicles: BDTS-67CK2-A or later suffix.


NOTE: The Description for DTC U2050:55-TCU will be added to MGSS.

This is caused by a communication error between the TCU, the Connectivity Master Unit (CMU), and the Body Control Module (BCM) when the control software in them are not of the version being ready for activation of connected service. To correct this concern, the control software of the TCU, CMU and BCM have been modified.

When you encounter this concern, reprogram (update) the BCM and the CMU to the latest version.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3b. Select the following:
A. Toolbox
B. Work support icon
C. Mazda Connect
D. **Activating Remote Control by Smart Phone**
E. RUN.






3c. Follow the on-screen instructions.

NOTE:

1. If TCU is not being replaced, ignore "Complete installation of new TCU" (a).
2. Battery voltage must be 14-14.5V (b). (see SA-063/20)

The screenshot shows the 'Activating Remote Control by Smart Phone' screen. At the top right, the battery voltage is displayed as 14.4V, circled in red with a red arrow labeled 'b'. Below the title, there is a section titled 'Complete installation of new TCU.' circled in red with a red arrow labeled 'a'. At the bottom right, there is a 'Next' button.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	 
<p>3d. Select Quick Check (A), then start the engine and select the DTC Clear icon (B).</p> <p>CAUTION: If the engine is not started, DTC P2610 is stored and cannot be erased.</p>	

4. Verify repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION**NOTE:**

- If the TCU has been replaced for warranty repair, claim additional hours using the labor operation number with "BRT" instead of the last three letters "BRX".
- If the TCU has been reprogrammed for warranty repair, claim additional hours using the labor operation number with "xFT" instead of the last three letters "xFX".

Additional reprogramming	Additional hours
CMU	0.1 Hrs.
BCM	0.1 Hrs.
CMU BCM	0.2 Hrs.

Example:

Replacing TCU	T0524BRX / 0.4 Hrs.
With reprogramming CMU	T0524BRT / 0.5 Hrs.
With reprogramming BCM	T0524BRT / 0.5 Hrs.
With reprogramming CMU BCM	T0524BRT / 0.6 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.