Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

WHITE LINES APPEAR IN INSTRUMENT CLUSTER

Bulletin No.: 09-018/20

Last Issued: 10/30/2020

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

| Previous TSBs: | Date(s) Issued: |
|----------------|-----------------|
| 09-018/20 | 04/23/20 |

APPLICABLE MODEL(S)/VINS

2019-2020 Mazda3 (Japan built) vehicles with VINs lower than JM1BP*****152017 (produced before Sep. 5, 2019)

2019-2020 Mazda3 (Mexico built) vehicles with VINs lower than 3MZBP******128583 (produced before Nov. 29, 2019)

2020 CX-30 (Mexico built) vehicles with VINs lower than 3MVDM******102129 (produced before Nov. 1, 2019)

DESCRIPTION

Some customers may notice white lines appearing across the instrument cluster (as shown below). The white lines may be caused during the production process where poor contact occurs at the internal LCD terminals.

Page **1** of **5**





To eliminate this concern, the production process for the instrument cluster has been modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

- 1. Verify the customer concern.
- 2. Replace the instrument cluster with a modified one according to MGSS online:
 - Mazda3: (INSTRUMENT CLUSTER REMOVAL/INSTALLATION)
 - CX-30: (INSTRUMENT CLUSTER REMOVAL/INSTALLATION)

NOTE: Modified parts can be distinguished by the label on the back of the instrument cluster (as shown below).

Mazda3 (Japan built) vehicles:

The lot number on the label includes the production date ("YYMMDD" format) and the serial number ("NNNN") of the day.

Page 2 of 5



Format: **YYMMDDANNNN

Sample: CY190812 A0096 means the 96th production on

August 12, 2019

NOTE: If the production date and the serial number on the label is the same or later than the First Modified Lot Number (as shown above), it is a modified part.

| Part Number | First Modified Lot Number |
|--------------|---------------------------|
| BDGG-55-430B | BV190721A0001 |
| BCPT-55-430A | HP190723A0001 |
| BDEL-55-430B | CV190720A0001 |
| BDGF-55-430B | AV190721A0001 |
| BDMN-55-430B | DV190722A0001 |

Mazda3 (Mexico built) vehicles:

The lot number on the label consists of 4 digits for the part number (PPPP) and 6 digits (NNNNNN) for the serial number (it does not include the production date).



Format: **PPPPNNNNNN**

Sample: BDFT021137 means BDTS-55-430 and the serial

number 021137

NOTE: If the serial number on the label is the same or later than the First Modified Lot Number (as shown above), it is a modified part.

| Part Number | First Modified Lot Number |
|--------------|---------------------------|
| BEDP-55-430B | BEGT 035077 |
| BFRW-55-430A | BFKL 032895 |
| BDTS-55-430B | BDFT 021137 |
| BDCJ-55-430A | BDJL 037762 |

Page 3 of 5

CX-30 (Mexico built) vehicles:

The lot number on the label consists of 4 digits for the part number (PPPP) and 6 digits (NNNNNN) for the serial number (it does not include the production date).



Format: PPPPNNNNNN

Sample: BDFT021137 means BDTS-55-430 and the serial

number 021137

NOTE: If the serial number on the label is the same or later than the First Modified Lot Number (as shown above), it is a modified part.

| Part Number | First Modified Lot Number |
|-------------|---------------------------|
| DAKM-55-430 | DAGE 035138 |
| DGJ2-55-430 | DGFE 033317 |

PARTS INFORMATION

| Part Number | Description | Qty. | Notes |
|--------------|-------------|------|----------------------------|
| BDGG-55-430B | Meter Set | 1 | Mazda3 2.5L (Japan built) |
| BDGF-55-430B | Meter Set | 1 | Mazda3 2.0L (Japan built) |
| BEDP-55-430B | Meter Set | 1 | Mazda3 2.5L (Mexico built) |
| BDTS-55-430B | Meter Set | 1 | Mazda3 2.0L (Mexico built) |
| DAKM-55-430 | Meter Set | 1 | CX-30 2.5L (Mexico built) |
| DGJ2-55-430 | Meter Set | 1 | CX-30 2.0L (Mexico built) |

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
 - This repair will be covered under Mazda's New Vehicle Limited Warranty term.
 - Additional diagnostic time cannot be claimed for this repair.

Page 4 of 5

| Bulletin No.: 09-018/20 | Last Issued: 10/30/2020 |
|--------------------------------|-------------------------|
| | |

| Warranty Type | А |
|------------------------------------|---------------------|
| Symptom Code | 88 |
| Damage Code | 9W |
| Part Number Main Cause | ****-55-430* |
| Quantity | 1 |
| Operation Number / Labor Hours: | XXS17ARX / 0.8 Hrs. |

Page 5 of 5