ATTENTION: GENERAL MANAGER Service Personnel Should Read and Initial in the boxes provided, right. SERVICE MANAGER © 2020 Subaru of America, Inc. All rights reserved.



SERVICE BULLETIN

APPLICABILITY: 2017-19MY Outback NUMBER: 07-179-20

SUBJECT: Power Rear Gate (PRG) Control Module - DATE: 10/05/2020

Design Change

INTRODUCTION:

This bulletin announces a design change made to the PRG control module. This change is in response to a limited number of customer concerns regarding the vehicle's battery becoming discharged after the rear gate is left open for an extended period of time. The discharge occurs because current PRG control module logic keeps CAN communication active. Logic changes have been incorporated into the new module to allow the CAN system to "go to sleep" after a period of time to prevent current draw and optimize operation of the PRG system.

PRODUCTION CHANGE INFORMATION:

This bulletin will be revised with starting VIN information for the change when it becomes available.

PART INFORMATION:

Description	Part Number	Application	
ECU- POWER REAR GATE	63350AL10B	2017-19MY Outback	

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedures for replacing the PRG control module remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time, every time. This includes but is not limited to important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code	
PRG CONTROL MODULE R&R	B850-965	0.5	UPW-48	
PRG SYSTEM TESTING & DIAGNOSIS	C850-950	0.4		

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.