

**Complaint - Engine Support Broken: Replacing Both Engine Supports (179/18)**

Revision: This bulletin replaces bulletin Group 1 179/18, dated February 15, 2019.

Model Year: **As of 2017 up to 2018**

Model Line: **Panamera (971)**

Equipment: V6 engine

Subject: **Engine support**

Information: **In the event of a customer complaint reporting that the vehicle or engine vibrates/shakes and/or if diagnostics confirms that an engine support is broken, both engine supports must be replaced.**



**Information**

There is a possibility that the bellows on the drive shaft was damaged as a result of a broken engine support.

In the event of a customer complaint, check the bellows for possible damage.

Parts Info:



**Information**

**The following points must be observed in relation to the part numbers listed below and the relevant vehicle (depending on equipment):**

- **Part number indexes will increase over time.** Before performing repairs, cross reference with PET (Porsche Spare Parts Catalog), for newer parts (higher index).
- **PET must be checked** to determine if additional components are needed.
- **Particular/modified components**, whose part numbers are listed accordingly, are **required for the remedial action**.

9A7.199.307.10 ⇒ Engine support (left)

9A7.199.308.10 ⇒ Engine support (right)

Invoicing:

**Information**

The labor operations required for standard repairs are not listed here.

The labor operations must be invoiced according to the Labor Operation List.

For invoicing and documentation using PQIS, enter the following coding:

<b>Location (FES5)</b>	10310	Engine carrier
<b>Damage type (SA4)</b>	1511	Broken

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.