

## STAR ONLINE PUBLICATION















Case Number: S1918000003

Release Date: 10/29/2020

Symptom/Vehicle Issue: Revision A: Intermittent Engine Buck, Surge, or Misfire.

**Discussion:** A small number of customers may experience an intermittent engine buck, surge, or misfire condition. This condition can occur under slight loads or while towing. Especially when driving up slight inclines. The condition can often be thought to be a transmission issue. In addition, you may find one or more of the following DTCs listed below. However, there have been instances of this condition where no DTCs will set. The potential DTCs are as follows:

- P0201 Fuel Injector 1 Circuit Open
- P0202 Fuel Injector 2 Circuit Open
- P0203 Fuel Injector 3 Circuit Open
- P0204 Fuel Injector 4 Circuit Open
- P0205 Fuel Injector 5 Circuit Open
- P0206 Fuel Injector 6 Circuit Open
- P020A Fuel Injector 1 Performance
- P020B Fuel Injector 2 Performance
- P020C Fuel Injector 3 Performance
- P020D Fuel Injector 4 Performance
- P020E Fuel Injector 5 Performance
- P020F Fuel Injector 6 Performance
- P0300 Multiple Cylinder Misfire.
- P0301 Cylinder 1 Misfire
- P0302 Cylinder 2 Misfire
- P0303 Cylinder 3 Misfire

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

FCA US LLC Version 4.3 10/28/2020



## STAR ONLINE PUBLICATION















- P0304 Cylinder 4 Misfire
- P0305 Cylinder 5 Misfire
- P0306 Cylinder 6 Misfire

If you receive a vehicle with this issue, be sure to closely inspect all injector electrical connections for being properly torqued. We have had reports from the field of injector electrical nuts being loose causing this type of concern. Other reports have found some connections being cross threaded.

If found loose, simply torque the connections to specifications and retest. If found cross threaded, the injector and fuel injector harness/valve cover gasket, must be replaced.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

FCA US LLC Version 4.3 10/28/2020