

This bulletin provides information to update the head unit software (S/W) on some 2020MY K900 (RJ) vehicles produced from June 25, 2019 through July 2020, equipped with Premium Gen 2.0 head units, which after saving radio presets, some of the radio presets may delete after the head unit reboots. To correct tis concern, confirm that the head unit has the latest software version described in this publication.

Note: This issue affects a small number of vehicles so not all dealerships were shipped USBs. The software update is also available through MapCare (TSB ELE 208) if the USB mentioned in this bulletin is not available.

MODEL	COUNTRY	S/W VERSION	
		OLD	NEW
RJ	USA	RJ.USA.P5.001.001.190524	RJ.USA.P5.001.003.200213



***** NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service \rightarrow Warranty Coverage \rightarrow Warranty Coverage Inquiry \rightarrow Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs \rightarrow Not Completed Recall \rightarrow Recall VIN \rightarrow Select Report), which includes a list of affected vehicles.

This issue number is <u>SA443</u>.

Printed TSB copy is for reference only; information may be updated at any time. Always refer to KGIS for the latest information.

Circulate To:	🛛 General Manager	I Service Manager	🗵 Parts Manager
Service Advisor	s 🛛 Technicians	☑ Body Shop Manager	I Fleet Repair

Page 2 of 4

SUBJECT: SERVICE ACTION: PREMIUM GEN 2.0 HEAD UNIT S/W UPDATE

IOME

Fauorites

Software Update Procedure:

- 1. Turn ignition 'ON' and save customer radio presets.
- 2. After AVN reboots, select "Setup" on the head unit.

3. Select "System Info".

4. In the "Software Information", check the S/W version currently installed.

Confirm that the currently installed S/W version is **RJ.USA.P5.001.001.190524**.

5. Insert the "S/W Update USB" into the USB Post.

(i) IMPORTANT

The head unit software update will be performed in the Dealer/Port method. <u>DO NOT</u> initiate by way of the head unit screen, follow step 6.

When the 'pop-up' message shown is displayed, <u>DO NOT select</u> "Now" <u>or</u> "Close".

<u>Note</u>: If selecting "Now", the software will take over one (1) hour to update.

The Dealer/Port method will instead take only half an hour (30 min.)





--:--

Start the system update? Update Information: RJ.USA.P5.001.003.200213



--:--



Page 3 of 4

SUBJECT: SERVICE ACTION: PREMIUM GEN 2.0 HEAD UNIT S/W UPDATE


- 7. Using the head unit 'Tune' knob and 'NAV' key, <u>follow the instructions below</u>:
 - 1) Turn the 'Tune' knob three (3) turns to the right.
 - 2) Press the 'Tune' knob to ENTER.
 - 3) Turn the 'Tune' knob seven (7) turns to the left.
 - 4) Press the 'Tune' knob to ENTER.
 - 5) Turn the 'Tune knob' one (1) turn to the right.
 - 6) Press the 'Tune' knob to ENTER.
 - Press the 'NAV' Key on the head unit
- 8. When the 'pop-up' message shown is displayed, select "Yes".

<u>Note</u>: Processing Update message will appear and take about thirty (30) minutes to complete.

9. Update Completed, select OK.

Repeat steps 2 – 4 to confirm that S/W version **RJ.USA.P5.001.003.200213** was installed correctly.

10. Remove the USB driver and restore customer radio presets.














Page 4 of 4

SUBJECT: SERVICE ACTION: PREMIUM GEN 2.0 HEAD UNIT S/W UPDATE

AFFECTED VEHICLE RANGE:

Model	Production Date Range
K900 (RJ)	June 25, 2019 to July 2020

REQUIRED TOOL:

Tool Name	Figure	Comments
USB Driver	RJ/FE SW (003.200213)	Auto Shipped to Select Dealers

WARRANTY INFORMATION:

N Code: N99 C Code: C99 Replacement Claim Repair Labor Op Op Causal P/N Qty. Туре Description Code Time P/N Premium GEN 2.0 0.3 V 0 200092R1 N/A 96120 2K000 Software Update M/H

* NOTICE		
VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference <u>SA443</u> when accessing the WebDCS system.		



Qty.

0