

Symptom-based workshop manual

164/20enu 9757

Service

9

Noise Symptom - Crackling Noise During Seat Adjustment: Reworking Front Seat Wire Harness (SY 164/20)

Model Line:	Taycan (Y1A)			
Model Year:	As of 2020			
Subject:	Wire harness for front seat			
Symptom:	Particularly when the seat adjustment is low, a crackling noise can be perceived when adjusting the longi- tudinal position of the driver's seat or passenger seat.			
Cause:	The anti-chafing element on the wire harness can contact the front seat transverse strut in different places and cause the noise.			
Remedial Action:	In the event of a customer complaint, wrap the wire harness for both front seats with textile fabric tape.			
Required tools and materials				
Tools:	Scissors			

Materials:	Required materials (usually already available at the Porsche dealer):				
	Part No.	Designation	Qty.		
		\Rightarrow Textile fabric tape, approx. 40 mm/ 1.57 in wide (commercially available)	As required		

Preparatory work

Work Procedure: 1 Remove both front seats; see \Rightarrow Workshop Manual '720119 Removing and installing front seat'.


9757 ENU 164/20

Reworking front seat wire harness

2

Work Procedure: 1 Wrap section \Rightarrow Wire harness for front seat on driver's side -1- of wire harness for front seat on driver's side with textile fabric tape as far as the wiring harness junction \Rightarrow Wire harness for front seat on driver's side -2-.

> Wrap section \Rightarrow Wire harness for front seat on passenger's side -1- of wire harness for front seat on passenger's side as far as the first clip \Rightarrow Wire harness for front seat on passenger's side -2- with textile fabric tape in an overlapping pattern.



Wire harness for front seat on driver's side

Wire harness for front seat on passenger's side

Concluding work

Work Procedure: 1 Install both front seats; see \Rightarrow Workshop Manual '720119 Removing and installing front seat'.

Invoicing

Invoicing: For documentation and warranty invoicing, enter the labor operations, PQIS coding and part numbers specified below in the warranty claim:

APOS	Labor operation	I No.
97574901	Reworking wire harness for electrically adjustable seat on driver's side	
97574902	Reworking wire harness for electrically adjustable seat on passenger's side	

AfterSales

Symptom-based workshop manual

	PQIS coding:						
Location (FES5) Damage type (SA4)		97570	70 Wire harness for electrically adjust				
		2016	crackling				
Parts Info:	Part No. 	Designation ⇒ Textile fabric t (commercially av	ape, approx. 40 mm/ 1.57 in wide ailable)	Qty. As required			
References:	⇒ Worksho	p Manual '720119 Removing	and installing front seat '				

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.

AfterSales

Nov 11, 2020 Page 3 of 3