

Taycan – Case Information to Analyze Discharged 12V Batteries

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2020 - 2021	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	November 12, 2020	Original document

Condition

Detailed case information is often required to aid technical analysis of vehicles which break down due to discharged 12V batteries. In the event of such a breakdown, please reference and complete as much of the attached questionnaire as possible.

Technical Background

An investigative analysis to resolve this matter is in process.

Service Information

Please document case information in detail.

To open the attachment, download the pdf and click on the paperclip icon to the left of your Adobe Acrobat window. If the paperclip is not visible, pass your mouse pointer over the lower part of the Acrobat window and the Acrobat toolbar should appear as seen below. Click on the Acrobat icon on the far right to access the paperclip, then click on the paperclip to open the attachment.



Warranty

As always, please document the case completely in PQIS.

For this repair, please code the "cause" as follows:

Cause location:	2706	Vehicle Electrical System Battery
Cause symptom:	040	Electrical faults

Search Items

Discharged 12V battery; case report

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
